

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

Satish Kumar, Ram Ratan Ram,

2 Name of Block :-

Chander.

3 Name of Road :-

Prinsy Path to Sukhay Tola.

A. For Road

1 Damage Location/Chainage :- 0.200km to 0.500km, 0.590 to 0.990, 1.00km, 1.700km.

2 Damage Length :- 1.35 km.

3 Nature of damage :- Road crust & flank.

4 Details of Restoration Works :- Brick bats.

i Material being used in Restoration works:- Brick bats.

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :- 1.35 km

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-


4 Details of Restoration Works :-


i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-


iii Procedure taken up in Restoration works :-

iv Restored Length :-


JE


AE


EE


Signature
(Name of inspector)

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement



(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME OF ROAD: PMUNSY TO					
					SUKHAY TOLA.
Agency			:		
Head			:	FDR.	
Actual length of Road					2.190km
Flood affected length					
of Road				:	1.35 km.

Record Entry:					
Laying & distribution of brick bats on affected road portion as per specifications to meet the					
1x	30x	2.50x	0.25	=	18.75m ³
4x	4x	2x	0.175	=	5.60m ³
4x	3x	1.5x	0.25	=	4.50m ³
1x	6x	1.5x	0.25	=	2.25m ³
5x	3x	2x	0.30	=	9.0m ³
2x	300x	1.5x	0.20	=	180.00m ³
1x	50x	2.5x	0.30	=	37.50m ³
4x	6x	3.5x	0.30	=	25.20m ³
4x	3x	1.5x	0.25	=	4.50m ³

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
5X	20X	2X	0.20	2	4.00 m ³
2X	10X	1.5X	0.2	2	6.0 m ³
1X	4X	2X	0.25	2	2.0 m ³
5X	3X	2.5X	0.20	2	7.50 m ³
1X	5X	2X	0.25	2	2.50 m ³
4X	1.5X	3X	0.2	2	3.60 m ³
1X	10X	2X	0.25	2	5.0 m ³
4X	2X	1.5X	0.3	2	3.60 m ³
1X	10X	2X	0.2	2	4.0 m ³
4X	2X	1.5X	0.2	2	2.40 m ³
8X	3X	2X	0.2	2	9.60 m ³
6X	2X	2X	0.3	2	7.20 m ³
4X	2X	1.5X	0.2	2	2.40 m ³
3X	3X	2X	0.3	2	5.40 m ³
3X	4X	2X	0.2	2	4.80 m ³
2X	6X	2X	0.3	2	7.20 m ³
2X	3X	2X	0.25	2	3.00 m ³
2X	3X	2X	0.2	2	2.40 m ³
					40.50 m ³
 18/01/2021 SR  18/01/2021 AE					
Record Entry:					
Laying & distribution of brick bats on affected road portion as per specification to meet the					
4X	3X	1X	0.2	2	2.40 m ³
1X	3X	3X	0.2	2	2.40 m ³
					1.80 m ³

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
2X	2X	3X	0.30	2	3.60m ³
6X	3X	1X	0.20	2	3.60m ³
1X	40X	3X	0.20	2	24.0m ³
2X	3X	2X	0.20	2	2.40m ³
5X	3X	2X	0.20	2	6.0m ³
5X	2X	2X	0.30	2	6.0m ³
7X	1X	1X	0.20	2	1.40m ³
8X	1X	1X	0.20	2	1.60m ³
1X	30X	1.5X	0.20	2	9.0m ³
3X	2X	1.5X	0.20	2	1.80m ³
1X	15X	2X	0.20	2	6.0m ³
8X	2X	1X	0.20	2	3.20m ³
1X	12X	2X	0.20	2	4.80m ³
4X	5X	2X	0.20	2	8.00m ³
2X	5X	2X	0.20	2	4.0m ³
2X	8X	1X	0.20	2	3.20m ³
4X	8X	2X	0.20	2	12.80m ³
1X	10X	3X	0.30	2	9.00m ³
1X	20X	1.8X	0.30	2	10.80m ³
1X	15X	1.2X	0.20	2	3.60m ³
4X	3X	1X	0.30	2	3.60m ³
3X	3X	2X	0.25	2	4.50m ³
1X	15X	2X	0.25	2	7.50m ³
6X	2X	1X	0.20	2	2.40m ³
4X	4X	2X	0.225	2	8.20m ³
					566.10m ³

Continuation

18/01/24
JC

AK
18/01/24
AE

Abstract of Cost.

4

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Laying & distribution of brick bats on affected road portion as per specification to meet the required slope - - - - -				41	
Quantity viz 714 B.P. @					
560.10 m ² @ RS 1874.97 = RS					1050171.00
Add: 41 @ 1% Cont				= RS	10501.71
Add: GST @ 12%, amts				= RS	126020.52
					<u>1186693.23</u>
Say RS 1186693.00					
<i>[Signature]</i> 18/01/24				<i>[Signature]</i> 18/01/24	
				<i>[Stamp]</i> CSE 17/02/24	