

Inspection Report for Flood Damage work

of PTUS :- R.W.D. Uda Kisungang
of Block :- Purani
of Road :- 2026 - To 3 to Fulpur

oad

age Location/Chainage :- (0.00 - 0.250) (0.300 - 5.80) (0.750 - 1.250) (1.500 - 2.200)

age Length :- 2.200 KM (2.350 - 2.500)

ure of damage :- Road crust

ails of Restoration Works :-

erial being used in Restoration works:- Brick bats

ipments/Tools being used in Restoration works :-

cedure taken up in Restoration works :-

ored Length :-

r Bridge

image Location/Chainage :- No

image Length :-

ure of damage :-

tails of Restoration Works :-

aterial being used in Restoration works:-

quipments/Tools being used in Restoration works :-

rocedure taken up in Restoration works :-

estored Length :-

Shukla
22/11/2020
JE

AE
23/11/2020
AE

EE
29/11/20
EE

Signature
15/11/2020
(Name of inspector)

Name of Work-
 Situation of Work-
 Agency by which work is executed-
 Date of Measurement-
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work:- Temporary Resubstation					
from 100m to 700m					
Salpex.					
Agency:-					
Head:- F.D.R					
Actual length of Road $\rightarrow$ 3.00 km					
Flood affected length of Road $\Rightarrow$ 2.25 km					

Road Entry					
5	X	3.00	X	0.450	$\Rightarrow$ 6.750 m ³
1.5	X	0.600	X	0.400	$\Rightarrow$ 0.360 m ³
2	X	0.900	X	0.350	$\Rightarrow$ 0.630 m ³
2	X	1.10	X	0.450	$\Rightarrow$ 0.990 m ³
6	X	1.10	X	0.500	$\Rightarrow$ 3.300 m ³
18	X	3.75	X	0.45	$\Rightarrow$ 30.375 m ³
8	X	1.50	X	0.500	$\Rightarrow$ 6.000 m ³
5	X	0.80	X	0.55	$\Rightarrow$ 1.375 m ³
6	X	1.25	X	0.350	$\Rightarrow$ 2.625 m ³
2	X	2.00	X	0.300	$\Rightarrow$ 1.200 m ³
6	X	3.00	X	0.400	$\Rightarrow$ 7.200 m ³

Continuation

Soil ESD Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L	B	H	
5x2x	3.35x	2.00x	0.18x		22.18m ³
3x15x	4.25x	3.00x	0.18x		2.00m ³
10x1x	2.25x	0.18x			11.25m ³
5x1x	1.75x	0.18x			1.00m ³
3x2x	2.75x	0.18x			4.00m ³
10x0.75x	0.75x	0.18x			3.21m ³
8x2x	2.00x	0.18x			4.00m ³
6x1.50x	0.18x	0.18x			3.11m ³
4x1.00x	0.40x	0.18x			1.00m ³
2x0.50x	0.45x	0.18x			0.45m ³
6x1.20x	0.50x	0.18x			3.60m ³
6x0.60x	0.15x	0.18x			1.78m ³
3x1.00x	0.40x	0.18x			0.40m ³

2x0.20x	0.18x	0.18x			0.20m ³
4x2.50x	0.75x	0.18x			1.00m ³
8x2.25x	0.75x	0.18x			0.50m ³
6x0.50x	0.80x	0.18x			0.40m ³
3x5x	3.00x	0.85x	0.18x		38.25m ³
4x5x	1.85x	0.90x	0.18x		36.00m ³
5x1.00x	0.70x	0.18x			1.50m ³
5x6x	1.50x	0.70x	0.18x		12.50m ³
15x3.75x	0.70x	0.18x			16.87m ³
2x1.50x	0.70x	0.18x			1.00m ³
3x1.00x	1.50x	0.18x			1.50m ³
5x2.50x	0.40x	0.18x			5.00m ³
4x4x	3.75x	0.50x	0.18x		10.00m ³
1x3.75x	0.40x	0.18x			1.50m ³

Continuation

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
33.2x	1.30x	0.700		10.800m ²
18x	1.50x	0.350		6.200m ²
5x	0.150x	0.400		1.000m ²
2x	1x	1.85x	0.300	3.300m ²
7x	1.00x	0.400		2.800m ²
6x	5x	3.00x	0.750	31.500m ²
1x	0.50x	0.750		0.375m ²
5x	0.500x	0.300		0.750m ²
3x	0.75x	0.350		0.788m ²
5x	6x	3.00x	0.400	40.500m ²
15x	2.20x	0.700		9.900m ²
5x	4x	0.750x	0.250	5.250m ²
6x	0.50x	0.400		1.200m ²

2x	1.10x	0.750		0.770m ²
2x	3x	2.50x	0.450	27.000m ²
6x	3.75x	0.300		6.750m ²
25x	0.500x	0.350		4.375m ²
8x	3.75x	0.500		9.000m ²
5x	0.100x	0.400		1.200m ²
3x	3.75x	0.450		15.788m ²
				420.570m ²

Subd
24/01/2021
JL

AK
24/01/2021
AF

24/01/2021 J.G	24/01/2021 J.S	24/01/2021 C.C
------------------------------	------------------------------	------------------------------