

Inspection Report for Flood Damage Work

Date:-

1. Name of PIUs:- Ex. Er. R.W.D. Work Div- Araria
2. Name of Block:- Jakhai
3. Name of Road:- To 2 Rani to Mehdi Nagar

A. For Road

1. Damage Location/Chainage :- CH- 900-924, ~~XXXXXX~~
2. Damage Length :- $(24+0) = 20.00M$
3. Nature of Damage :- Crust damaged
4. Details of Restoration Works:-
(i.) Material being used in Restoration Works:- local sand, brick bat, 1/4".
(ii.) Equipments/Tools being used in Restoration works:- Tractor with Trolley
(iii.) Procedure taken up in Restoration works:- filled all cuts properly in damaged area
(iv.) Restored Length :- 20.00

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works:-
(i.) Material being used in Restoration Works:-
(ii.) Equipments/Tools being used in Restoration works:-
(iii.) Procedure taken up in Restoration works:-
(iv.) Restored Length :-

N.A.

Signature of JE/AE/EE

Signature

(Name of Inspector)
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रणाल- किशनगंज-2

ABSTRACT

Name of Road : T02 Rani to Mehdinagar


Length : 2.810 km

District : Araria

Block : Jokihat

Sl. No	Particulars		Total Cost (in Rs.)
1	Cost of Road Restoration work	:	626001
2	Add G.S.T. @ 12%	:	75120
3	Add Labour Cess @ 1%	:	6260
Total Cost			707381
Sug :-			7,07,400=00


23/12/2020
J. E.


23/12/2020
A. E.


23/12/2020
E. E.

T/A for Rs - 7,07,400/- (Rupees Seven Lacs Seventy thousand four hundred) only


12/3/21

EE
RVO ARADIA