

MAHRATJ TOLA TO SANGHE TOLA
UNDER FDR

FDR-2020-21

Schedule XLV-Form No. 134

MB No-1432

RWD WURIS DIV SUPAVI DIVISION

MARANA SUB-DIVISION

Measurement Book

प्रमाणित किया जाता है कि इस मापी हुई वस्तु
 में कुल 50 (पचास) ममीन द्वारा प्रमाणित
 पुष्ट है जो इसी विवरण के अनुसार प्रसादित
 सहायक अधिकारी को भर्ष 1941 (फोर्ट) में
 मरीन के नाम से निहित किया जाता है

[Signature]

कार्यपालक अधिकारी
 ग्रामीण कार्य विभाग
 कार्य प्रमाणित (सुपौल)

Sch. XLV-Form No. 134

Supaul DIVISION

Marwan SUB-DIVISION

1432

Measurement Book

No.

8) Labour: filling
empty cement
bags with loose
sand —

Ch-1.12012 - $1 \times 25.00 \times 5810^4$
 $\times 2.40m = 36.0m^3$

No. of bags $\frac{36.0}{0.0047100}$
 $= 10.585\%$

5) frondif and
loging Reinford

Composite Concrete

NP 100 mmHg

2 rows

$$\text{Ch. d. 50.1 km} - 2 \times 3 \times 2.50 \text{ m} = 15.0 \text{ m}$$

9.) Providing and
Laying Reinforced
Concrete - Concrete

HP 600mm dig

pipe double row

Ch-1.660km - $2 \times 2 \times 2.50M = 10.0M$

10/10/20

~~lenh~~
~~10/11/20~~
~~AB~~

26/11/20

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
FDR-2020-21					
1/1)	Sand filling in ditch & breach portion — on Per EIR				
4-589.49 m^3	vide TMB P-①				
	@ Rs-554.03/ m^3 Rs-				326599.36
2/2)	Bronding and laying brick 5cm — on Per EIR				
1115.15					
4-269.167 m^3	vide TMB P-②				
	@ Rs 1864.35/ m^3 Rs-				2079039.22
3/3)	Labour for Cubing 52mm to 75mm dia bamboo Piles — on Per EIR				
269.167 m^3	vide TMB P-②				
	@ Rs 27.90/ m^3 Rs-				7509.76
4/1)	Labour for filling and fixing split bamboo Chechi — on Per EIR				
92.0 m^2	vide TMB P-③				
	@ Rs-73.60/ m^2 Rs-				6771.2

Rs-2419917.54

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B/F PS - 2419917.54	
5/5) Labour for fitting					
& fixing 75mm					
dia bamboo runner					
— as per EIT					
Qty - 480.0 M vide TMB P-3					
@ Rs. 5.00/M - RS -				2400.00	
6/6) Supply of bamboo					
at site — as per					
EIT					
Qty - 181 Nos vide TMB P-3					
@ Rs. 158.44/No RS -				28677.84	
7/7) Labour fitting R.C.					
bags with local					
Sand — as per					
EIT					
Qty - 10.588 /x vide TMB P-4					
@ Rs. 3300.20/x - RS -				34942.52	
8/10) Providing and laying					
Reinforced Cement					
HP 100mm dia					
2 nos Pipe —					
Qty - 15 M vide TMB P-4					
@ Rs. 3523.00/M - RS -				52845.00	
9/11) P/V & laying R.C.					
Pipe - 600mm dia —					

Continuation Rs. 252878270

[illegible]

Inspection Report for Flood Damage Work

Date:-

1. Name of PIUs :- E.E, RWD, Works Division, Supaul.
2. Name of Block :- Manama.
3. Name of Road :- Mahraji talq to Sanghi talq


A. For Road

1. Damage Location/Chainage :- 0.50km, 1.20km, 1.295, 1.475
2. Damage Length :- 5284
3. Nature of Damage :- Due to Road.
4. Details of Restoration Works :-
 - i. Material being used in Restoration works:- brick, bag, bamboo, chain
 - ii. Equipments/Tools being used in Restoration works :- JCB, Power Roller.
 - iii. Procedure taken up in Restoration works :- Repair
 - iv. Restored Length :- 5284

B. For Bridge

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Detail of Restoration Works :-
 - i. Material being used in Restoration works :-
 - ii. Equipments/Tools being used in Restoration work :-
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored Length :-

N.A


JE


AE


EE


signature

(Name of Inspector)