

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :-

Name of PIU:- Executive Engineer, RWD, (W) Division, ARARIA

Name of Block:- Sylketi

Name of Road:- College chowk to Mahadalit tola (Tupparnari)

FOR ROAD

Damage Location/ Chainage :- 1st Km

Damage Length :- 7.1 M

Nature of damage :- Crust and Flank washed out.

Details of Restoration work

- i Material being in Restoration work :- Soil, Local Sand, Sand bag, Brickbat Bamboo etc.
- ii Equipments/ Tools being used in Restoration works:- Tractor with trolly & others.
- iii Procedure taken up in Restoration work:- Filling all damaged portion of Crust and Flank with above Material
- iv Restored Length M

FOR BRIDGE

1 Damage Location/ Chainage :-


2 Damage Length :-


3 Nature of damage :-

4 Details of Restoration work


- i Material being in Restoration work :-
- ii Equipments/ Tools being used in Restoration works
- iii Procedure taken up in Restoration work
- iv Restored Length

Not Applicable


J.E.


A.E.



EE



Name of Inspector
EE, RWD, Kishanganj-I


GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : COLLAGE CHOWK TO MADALIT TOLA (TUPPAMARI)
DISTRICT ARARIA
DIVISION ARARIA
BLOCK SIKTI
LENGTH OF ROAD (IN KM) 1.800


Sl. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	BRIKCK BAT	12.570
2	LOCAL SAND	0.000
	TOTAL COST OF FROJECT =	12.570
	Add G.S.T. @ 12%	1.508
	Add Labour Cess @ 1%	0.126
	Total Cost of Restoration Work =	14.204


JE 22/11/20
RWD
SIKTI


AE 22/11/20
RWD


EE 22/11/20
RWD

Technically approved for Rs 14,20,400=00 (Rupees Forteen lac Twenty thousand four hundred) only


12/8/24