

Particulars	Details of actual measurement				Contents of area	
	No.	L.	B.	D.		
ABSTRACT OF COST						
<u>Name of work - Restoration</u>						
Work of floor damage.						
Total - of approach by Brick.						
<u>Name of place -</u> <u>Surgahiyra to Bhatauliya</u>						
Road.						
<u>Authority - E.G.R.W.D.(W) DIV</u>						
<u>S. Tamarkhi</u>						
<u>(1) providing and laying</u> bricks for filling ditch - in						
approach road - all in						
<u>Oxydide p. no ① T.M.S</u>						
111.54 m ³ @ 1546.0 / m ³ → 172441.0						
<u>(2) providing quarry</u> Material Rubbish for						
filling the voids in brick						
bats - - - eac						
<u>Oxydide p. no ① T.M.S</u>						
27.89 m ³ @ 742.0 / m ³ → 20690-						
R 193131.0						
Add 1% Labour Cost + R 1931.0						
Add 1% C. S.T R 23176.0						
R 218238.0						
<u>10/13/21</u>						
<u>10/15/21</u>						
<u>Continuation Folio 21</u>						
<u>A.E</u>						