

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक ३८३

दलसिंहसराय / दिनांक १८/०५/२१

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- New Maintenance Policy 2018(MR New) योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।

महाशय,

उपरोक्त विषय के संबंध में सूचित करना है कि New Maintenance Policy 2018(MR New) योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान Rs.-37.23680 (Thirty Seven Lakh Twenty Three Thousand Six Hundred Eighty Rupess) कि आवश्यकता है अधियाचना का निर्माण कार्य विशिष्टियों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन Rs.-37.23680 (Thirty Seven Lakh Twenty Three Thousand Six Hundred Eighty Rupess) उपलब्ध कराने कि कृपा कि जाये।

- अनु०- 1) अधियाचना प्रपत्र।
2) 19 ए फ़ॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन
17.05.2021
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय
दिनांक २१

Rural Works Department, Works Division Dalsinghsarai

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date		Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (in Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19		
RRM/SA/DAL/19/003																				
1		Sumnar Mayari Panchayat Bhawan to Ranchandrapur R.E.O Road via Kushthwar Mahto house to Ranchandrapur.	32010401009	1855/ 24.06.2019	2.400	46.3	38.219	20.4565	MBD 02/2019-20 20.03.2020	19-Dec-20	-	-	-	-	-	0.00000	0.00000	0.00000		
2		NH 103 Yogi Asthan se Khalisipur Muslim Tola Mazid Tak	10105080		0.700	27.7	24.842	5.401		19-Dec-20	-	-	-	-	-	-	0.00000	0.00000	0.00000	
3		Khalisipur Budhwaina (Sushil Ji Ke Char) Se Januaari Nadi (Madhya Vidhyalay Khalisipur Tak)	10105083		0.750	28.43	21.794	6.856		19-Dec-20	-	-	-	-	-	-	0.00000	0.00000	0.00000	
4		Khajuri se Chakanlad Tak	10105089		2.500	51.44	46.54600	25.00285		19-Dec-20	-	3770	25mm	5.10%	0.00000	0.00000	0.00000	37.23680	Patch Work Repair	
					6.350	153.870	131.40100	57.71635								0.00000	0.00000	37.23680		

Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

Sr. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto May 2021

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1146.54778	1146.54778	Certified that out of Rs-1146.54778 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1139.63735 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-6.91043 Lakh remaining unutilized at the end of period under the time of completion
		1146.54778	1146.54778	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was


Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurements have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved


3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO
Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

File : C:\MyMaster\Bump May\17051157.Xls, Section No. : 32, Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$
 Name of Customer : Alkishna Construction Pvt Ltd, Name of Work/ Road : Khajuri To Chakhalad Tak, Lab Job



[Handwritten signature]
 12/5/2021

Date	Time	Section	No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5		
25/4/21	8: 18: 30		32	0.1	660	0	3500	3900	ROAD	25.708592	85.73835	Normal	X = 2800		
25/4/21	8: 19: 5		32	0.1	700	10.1	3200	3700	G	25.70857	85.739343	Normal	Y = 3313		
25/4/21	8: 19: 5		32	0.1	440	20.2	3100	3500	G	25.708448	85.740268	Normal			
25/4/21	8: 19: 41		32	0.1	450	10.1	3100	3400	G	25.707737	85.740757	Normal			
25/4/21	8: 20: 0		32	0.1	490	20.2	3400	3700	G	25.707573	85.7417	Normal			
25/4/21	8: 20: 16		32	0.1	590	10.1	3300	3900	G	25.707528	85.742677	Speed Breaker			
25/4/21	8: 20: 16		32	0.1	350	30.3	3500	3900	G	25.707352	85.743652	Normal			
25/4/21	8: 20: 51		32	0.1	360	30.3	3400	3900	G	25.707303	85.744545	Speed Breaker			
25/4/21	8: 21: 0		32	0.1	390	20.2	3700	3900	G	25.70771	85.74537	Normal			
25/4/21	8: 21: 0		32	0.1	370	20.2	3700	3900	G	25.708008	85.746127	Normal			
25/4/21	8: 21: 26		32	0.1	400	20.2	3500	3800	G	25.708297	85.746968	Normal			
25/4/21	8: 21: 26		32	0.1	350	20.2	2900	3300	G	25.709188	85.746918	Normal			
25/4/21	8: 22: 0		32	0.1	350	30.3	3500	3900	G	25.710045	85.746565	Normal			
25/4/21	8: 22: 1		32	0.1	310	30.3	3100	3654	G	25.710872	85.746195	Normal			
25/4/21	8: 22: 1		32	0.1	350	30.3	3200	3500	G	25.711775	85.745942	Normal			
25/4/21	8: 22: 1		32	0.1	390	30.3	3600	3800	G	25.71258	85.746212	Normal			
25/4/21	8: 22: 36		32	0.1	370	30.3	3400	3900	G	25.713453	85.746648	Normal			
25/4/21	8: 28: 0		32	0.1	470	0	3600	3900	G	25.707537	85.741902	Normal			
25/4/21	8: 28: 29		32	0.1	560	10.1	3400	3700	G	25.706672	85.74177	Normal			
25/4/21	8: 28: 29		32	0.1	480	10.1	3700	3900	G	25.70579	85.741632	Normal			
25/4/21	8: 29: 4		32	0.1	540	10.1	3200	3700	G	25.704905	85.741397	Normal			
25/4/21	8: 29: 4		32	0.1	450	10.1	3500	3900	G	25.704042	85.741245	Speed Breaker			
25/4/21	8: 29: 39		32	0.1	420	20.2	3700	3900	G	25.703187	85.741127	Normal			
25/4/21	8: 30: 0		32	0.1	550	10.1	3400	3800	G	25.70243	85.740773	Speed Breaker			
25/4/21	8: 30: 15		32	0.1	360	30.3	3600	3900	G	25.702577	85.739848	Normal			

17/5/24
62