

INSPECTION REPORT FOR ROUTINE MAINTENANCE


Date of Inspection : 25.11.21		District: 6449
Division : Tilkari		Length (km): 2.00 km
Name of the Road: Repair of Road from NH 83 to Bhu Tolg Mahadit Tolg via Kani		
Scheme/Programme: MR (Maintenance)		Remarks (S/U)

Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	U
a)	Condition of Surfacing	U
b)	Riding Quality	S
c)	Road Camber	U
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	U
f)	Compaction of flank/slope & raincuts if any	
Observation Remarks:- from 0 to 1.3 km chainage, B.T. surface seen with sufficient patches. At End chainage pcc surface is exposed to Aggregates (1.7 km to end). Compaction of flank/slope not maintained. No work of maintenance done.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	-
Observation Remarks:- painting required.		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Not properly maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : Satisfactory (S)/ Unsatisfactory (U) U

Name of Officer:- R.P. Saw (E.E)

Designature:- S. R. Saw (AG)
Flying Squad


25/11/21

25.11.21
(Signature)