

INSPECTION REPORT FOR ROUTINE MAINTENANCE

(12)

Date of Inspection : 25.11.21		District: 9799
Division : Tikari		Length (km): 0.725 KM
Name of the Road: Lobs to Goli		
Scheme/Programme: GTSNY (Maintenance)		
Sl. No.	Parameters to be checked	Remarks (S/U)
1.	Pavement	
a)	Condition of Surfacing	S
b)	Riding Quality	S
c)	Road Camber	S
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
e)	Contraction Joints provided or not (CC Pavement)	-
f)	Compaction of flank/slope & raincuts if any	U
Observation Remarks:- In partial length, there is cracks at four stretches and exposed aggregates are seen. Its repair is in progress. Flank E/W is required for maintaining its level. Earthen road is country with black cotton soil. Rest part is satisfactory.		
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-
c)	Condition of railings/slab/approach for Bridges	-
d)	Condition of Vent Clearance	S
Observation Remarks:- 		
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	U
Observation Remarks:- Not properly maintained.		
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)/ Unsatisfactory (U)

S

Name of Officer:- R.P. Saw (E.E)

Designature:- Sushanta Rajak (A.E)
Flying Squad
R.W.N.I

[Signature]
25/11/21

(Signature)

25.11.21