

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक.....1669...../बाँका

दिनांक 07.10.21

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 3,50,55,000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन


07.10.21

कार्यपालक अभियंता
ग्रा0का0वि0, कार्य प्रमण्डल,
 बाँका-2

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमण्डल, बाँका-2

पत्रांक...../बाँका

दिनांक

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, बाँका-2

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :- शीर्ष "3054 एम0आर0" योजना अन्तर्गत आवंटन के संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर03054 योजना अन्तर्गत संवेदक द्वारा कराए गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 3,50,55,000/-लाख का आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0:-1. अधियाचना प्रपत्र

2.IRI Report

विश्वासभाजन

ह0/-

कार्यपालक अभियंता
ग्रा0का0वि0,कार्य प्रमण्डल,
बाँका-2

ज्ञापांक-.../1669/बाँका दिनांक ...07.10.21

प्रतिलिपि :- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु समर्पित।

कार्यपालक अभियंता
ग्रा0का0वि0,कार्य प्रमण्डल,
बाँका-2

Form GFR 19-A

(See Government of India's Decision (1) below rule-15)
Form of utilization Certificate up to the Month August' 2021
MR/3054(NEW MAINTENANCE POLICY)

PIU-RWD(W), BANKA-2

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural roads under MR/3054(NEW MAINTENANCE POLICY)	विभागीय पत्रांक 37 दिनांक 27.05.2020 45(Encl)/18.06.2020 56(Encl)/12.08.2020 59(Encl)/18.08.2020 61(Encl)/26.08.2020 82(Encl)/13.11.2020 84(Encl)/26.11.2020 86(Encl)/11.12.2020 05(Encl) /12.01.2021 17 (Encl) / 26.02.2021 20 (Encl) /19.03.2021 22(Encl) /24.03.2021 27(Encl) /04.05.2021 30 (Encl) /21.05.2021 32 (Encl) / 28.05.2021 52 (Encl) /24.08.2021	217.86340 30.12339 525.63100 320.50000 6.57325 88.44000 395.49360 368.11196 570.35090 604.70836 361.33115 82.05330 88.60000 58.28940 440.19502 97.98875	Certified that out of Rs. 4256.25348 Lacs received during the years 2020-21 in favour of Ex. Engineer. RWD Bihar, RWD-2 Banka a sum of Rs. 4250.93652 Lacs has been utilized for the purpose of MR/3054(New Maintenance Policy) schemes as given in the margin for which it was sanctioned and that the balance of Rs 5.31696 remaining unutilized at the end of the period under.
	Total		4256.25348	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.



Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer .
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Measurement have been recorded in the MBs.
- All other code formalities have been observed.

3. Physical progress achieved :

- Construction of Road Works.
- Construction of CD Works.


Sr. D.A.O.
Works Division Banka-II
Rural Works Department


Executive Engineer
Works Division Banka-II
Rural Works Department


Requisition Format for Scheme Head-MR (3054) Under Bihar Rural Road Maintenance Policy 2018 (Initial Rectification and Surface Renewal)
Division :- Banka-2

Sl No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion (Expected)	Value of IRI (in mm/km)	Thickness of Bitumen layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in Lac)	Up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial rectification on with Surface renewal (in lac)	5 Years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
	MIR-N/19-20 Banka-2/16	Repair of Road from Simaramore Simarkola Road To Babhangana under MIR/3054	20703502125	6276 02.12.2019	3.180	116.299	78.33736	31.92046	32/MBD/20-21 14.09.20	13.09.21	29.05.21	2441.125	25mm	5%	0.00000	0.00000	78.30000	Surface Completed
2	MIR-N/19-20 Banka-2/16	Repair of Road from Bounsi Irrigation Dam Road Ashanaha under MIR/3054	20703502047	6276 02.12.2019	1.391	52.134	35.04891	14.39472	32/MBD/20-21 14.09.20	13.09.21	29.05.21	3244.071	25mm	5%	14.00000	14.00000	21.00000	Surface Completed
3	MIR-N/19-20 Banka-2/16	Repair of Road from BGP Dumkar Road To Rampurpabra under MIR/3054	20703502062	6276 02.12.2019	3.840	143.226	95.95507	38.42796	32/MBD/20-21 14.09.20	13.09.21	29.05.21	3055.256	25mm	5%	38.34000	38.34000	57.60000	Surface Completed
4	MIR-N/19-20 Banka-2/16	Repair of Road from Bounsi Irrigation Dam Road To Ihari	20703502042	6276 02.12.2019	2.160	74.569	49.66522	21.53266	32/MBD/20-21 14.09.20	13.09.21	26.09.21	2686.000	25mm	5%	0.00000	0.00000	40.00000	Surface Completed
5	MIR-N/19-20 Banka-2/16	Repair of Road from Bounsi Irrigation Dam Road To Sirai	20703502045	6276 02.12.2019	1.221	42.216	28.14845	11.93075	32/MBD/20-21 14.09.20	13.09.21	26.09.21	2632.083	25mm	5%	0.00000	0.00000	25.00000	Surface Completed

6	MIR-N/19- 20 Banka- 2/16	Repair of Road from Bounsi Irrigation Dam Road To Khaurant	20703502043	6276 02.12.2019	1.861	71.277	48,64473	19,56493	32/NIBD/20-21 14.09.20	13.09.21	26.09.21	2696.294	25mm	5%	0.00000	0.00000	40.00000	Surface Completed
7	MIR-N/19- 20 Banka- 2/02 under 3054/MIR	Chak Sapia To Parghari Via Barant Village Road	20703502224	1870 24.06.2019	6.150	165.319	97,79860	40,73483	06/NIBD/20-21 11.05.20	10.05.21	08.05.21	3152.919	25mm	5%	39.11600	39.11600	58.65000	Surface Completed
8	MIR-N/19- 20 Banka- 2/10	Repair of Road from Parghari to Pathara	20703501046	3028 16.07.2019	2.300	69.161	39,74600	19,11045	09/NIBD/20-21 27.05.20	26.05.21	11.08.2021	3116.217	25mm	5%	0.00000	0.00000	30.00000	Surface Completed
	Total																350.55000	

2/19/12

Executive Engineer
R.W.D.(V) Division,
Banka-2

6-10-21

Lab Job number :01

Date :29-05-2021

Name of Customer :Satish Kumar

Name of Work/ Road :Baunsi Irrigation Dam Road To Ashnaha


Sr.no	Location of test(in km)	Corrected U.I value(mm/km)	Road catagory
1	0.1	3466	G
2	0.2	3756	G
3	0.3	3175	G
4	0.4	2787	G
5	0.5	3175	G
6	0.6	2981	G
7	0.7	2884	G
8	0.8	2981	G
9	0.9	3562	G
10	1	3756	G
11	1.1	3466	G
12	1.2	2981	G
13	1.3	3078	G
14	1.4	3369	G

Pop
29/5/21
HE

Pritham
06.06.21
A.E

AN
06.06.21
EE

File : F:\BANK-2\01\29051324.Xls, Section No. : 1, Eqn : $Y = 0 * X^2 + 0.969 * X + 74.60$
 Name of Customer : Satish Kumar, Name of Work/ Road : Baunsi Irrigation Dam Road To Ashnaha, Lab Job number



[Signature]
 06.06.24
 EE

Pitkm
 06.06.24
 EE

[Signature]
 06.06.24
 EE


Name of Customer :
 Name of Work/Road :
 Lab Job number :
 Date :
 Section No. :

Test Date :
 Section No. :
 Road Name :
 Road Type :
 Side :
 UTY Range :
 Dist Range :
 Start Location :
 End Location :
 Equation :

Print

ReDraw Graph

Map View




R. S. Sath
 29.5.21
 R.E

R. S. Sath
 06.06.21
 R.E

R. S. Sath
 06.06.21
 R.E

File: BANK-210122051324.XLS, Section No.: 1, Eqn: $Y = 0 \cdot X^2 + 0.989 \cdot X + 74.60$



Per
06.06.21

Per
06.06.21

Per
06.06.21

Name of Customer : Satish Kumar
Name of Work/ Road : Baunsi Irrigation Dam Road To Ashnaha

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR		CATEGORY ROAD	IRI	Latitude	Longitude	Event
						mm/km	UIV					
29/ 5/ 21	12: 14: 0	1	0.1	350	0	3500	3466	G	4.58	24.772447	86.97153	Curve
29/ 5/ 21	12: 14: 0	1	0.1	380	20.2	3800	3756	G	4.92	24.771757	86.97096	Normal
29/ 5/ 21	12: 14: 0	1	0.1	320	30.3	3200	3175	G	4.23	24.770975	86.97052	Curve
29/ 5/ 21	12: 14: 35	1	0.1	280	30.3	2800	2787	G	3.77	24.770063	86.97052	Normal
29/ 5/ 21	12: 14: 35	1	0.1	320	30.3	3200	3175	G	4.23	24.769222	86.97071	Normal
29/ 5/ 21	12: 15: 0	1	0.1	300	30.3	3000	2981	G	4	24.768385	86.97088	Curve
29/ 5/ 21	12: 15: 10	1	0.1	290	30.3	2900	2884	G	3.88	24.767553	86.9714	Curve
29/ 5/ 21	12: 15: 10	1	0.1	300	30.3	3000	2981	G	4	24.766695	86.97148	Normal
29/ 5/ 21	12: 15: 10	1	0.1	360	30.3	3600	3562	G	4.69	24.765843	86.97145	Curve
29/ 5/ 21	12: 15: 45	1	0.1	380	20.2	3800	3756	G	4.92	24.765043	86.97103	Curve
29/ 5/ 21	12: 16: 0	1	0.1	350	20.2	3500	3466	G	4.58	24.764315	86.97054	Normal
29/ 5/ 21	12: 16: 20	1	0.1	300	20.2	3000	2981	G	4	24.76346	86.97051	Curve
29/ 5/ 21	12: 16: 20	1	0.1	310	20.2	3100	3078	G	4.12	24.76268	86.97003	Normal
29/ 5/ 21	12: 16: 55	1	0.1	340	20.2	3400	3369	G	4.46	24.761898	86.96958	Normal
Total UIV 45417								Total IRI	60.38			
Average UIV 3244.071								Average IRI	4.312857			

(R) RURAL ROAD

Good Average Poor

<4000 4001-5000 >5001

$$Y = 0 * X^2 + 0.969 * X + 74.60$$

$$X = 3400$$

$$Y = 3369$$

Pritham
06.06.21
N.E

Pritham
06.06.2021
N.E

Pritham
29.5.21
N.E