

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 1775 अक

दलसिंहसराय / दिनांक 25/10/2021

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-35.63160(Thirty Five Lakh Sixty Three Thousand One Hundred Sixty Rupess)** की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-35.63160(Thirty Five Lakh Sixty Three Thousand One Hundred Sixty Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No.	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRL (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Amount work done (in lac)	Remarks
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1		Samastipur jila antargat morwa prkhand me kali ashan nandkishor mishr ke ghar hote hua shivchandar sab ke dukan PMGSY tak path nirman	3.201E+10		0.690	21.26390	9.39500	4.09392			-	3764	25mm	5.10%	9.39500	9.29001	0.00000	
2		Samastipur jila antargat morwa prkhand ke gram panchayat indrawara ke prthamantri sadak madhy chok se vai shivji sabhi ke ghar hote hua nun nadi ghat ashal tak sadak nirman	3.201E+10		0.570	18.44820	8.29300	3.36880			-	3729	25mm	5.10%	8.29300	8.20242	0.00000	
3		Chandauli Hatt Se Mirzapur Village me Reo Sadak Tak	10105100	2200 / 08.07.2019	1.800	57.50880	34.22700	13.79259	MBD 73/2019-20 27.02.2020	16.09.2020	-	3508	25mm	5.10%	8.29300	8.20242	23.38160	
4		Gunai Basai Ward-1 Se Ward No-2 Tak	10105101		1.250	42.07280	25.38200	9.50637			-	-	-	-	0.00000	0.00000	0.00000	
5		Nikaspur Mahadalit Basti Se Shailesh Baba Shhan se REO Path Tak	10105104		0.500	15.62720	9.90100	2.83012			-	-	-	-	0.00000	0.00000	0.00000	
6		SH Patoni Path Se Pahaupur Hote Hue Bajipur Chowk Tak	10105106		1.700	61.09060	36.44300	14.43161			-	2744	25mm	5.10%	18.22150	33.67585	0.00000	
7		SUST Path se Rai Tola Tak	10105108		0.750	29.83630	18.86800	5.90173			-	-	-	-	0.00000	0.00000	0.00000	
8		PWD Sadak Se Chandauli APHC Mandir Tak	10105116		1.000	29.97940	19.20500	5.64539			-	3370	25mm	5.10%	8.29300	8.20242	12.25000	
					3.060	97.22090	51.915	21.255							25.98100	25.69485	35.63160	

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- 2 Up-to date Physical Progress has been uploaded in MIS.

St. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)

Form of Utilisation Certificate upto August 2021

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1373.95492	1373.95492	Certified that out of Rs-1373.95452 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1352.62628 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-21.32824 Lakh remaining unutilized at the end of period under the time of completion
		1373.95492	1373.95492	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-


- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works



23/10/21
Sr.DAO

Rural Works Department,
Works Division Dalsinghsarai


23/10/21

Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

File C:\My\master\18.10.2021\10101215.Xls. Section No. 62. Eqn : $Y = 0 \cdot X^2 + 1.136 \cdot X + 132.5$
Name of Customer RATNESH CONSTRUCTION PVT LTD. Name of Work/ Road Chandauli Hatt Se Mirzapur



Signature
Ratnesh Construction

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5		
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD				X = 2000		
10/10/21	10:35:50	62	0.1	280	10.1	2800	3500	G	25.800978	85.646463	Normal			
10/10/21	10:36:0	62	0.1	250	10.1	2500	2900	G	25.800978	85.646463	Normal	Y = 2404		
10/10/21	10:36:26	62	0.1	320	20.2	3200	3600	G	25.801703	85.64678	Normal			
10/10/21	10:36:26	62	0.1	310	10.1	3100	3400	G	25.802098	85.647457	Normal			
10/10/21	10:37:0	62	0.1	280	10.1	2800	3200	G	25.802843	85.647793	Normal	(R) RURAL ROAD		
10/10/21	10:37:35	62	0.1	340	10.1	3400	3900	G	25.803443	85.648282	Speed Breaker	Good	Average	Poor
10/10/21	10:38:11	62	0.1	260	10.1	2600	2800	G	25.804298	85.6484	Normal	<4000	4001-5000	>5001
10/10/21	10:38:46	62	0.1	280	10.1	2800	3200	G	25.805155	85.648552	Normal			
10/10/21	10:39:0	62	0.1	350	10.1	3500	3900	G	25.806103	85.648703	Speed Breaker			
10/10/21	10:39:21	62	0.1	340	10.1	3400	3850	G	25.806908	85.649107	Speed Breaker			
10/10/21	10:40:0	62	0.1	340	10.1	3400	3600	G	25.80697	85.65002	Normal			
10/10/21	10:40:32	62	0.1	290	10.1	2900	3100	G	25.807307	85.650858	Speed Breaker			
10/10/21	10:41:7	62	0.1	320	10.1	3200	3500	G	25.807025	85.65173	Normal			
10/10/21	10:41:42	62	0.1	350	10.1	3500	3800	G	25.806872	85.652727	Culvert			
10/10/21	10:42:18	62	0.1	370	10.1	3700	3900	G	25.807077	85.653502	Normal			
10/10/21	10:43:0	62	0.1	350	10.1	3500	3800	G	25.807863	85.654007	Normal			
10/10/21	10:43:0	62	0.1	360	10.1	3600	3800	G	25.808725	85.654343	Speed Breaker			
10/10/21	10:43:28	62	0.1	320	10.1	3200	3400	G	25.809003	85.65512	Normal			

Handwritten signature