

कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल बेगुसराय

940 7400

दिनांक- 63/09/2021 ई मेल – ee.begusarai.rwd2@gmail.com



प्रेषक.

कार्यपालक अभियंता. ग्रामीण कार्य विभाग, कार्य प्रमंडल, बेगुसराय ।

सेवा में

नोडल पदाधिकारी. नई अनुरक्षण नीति 2018" (3054-MR) ग्रामीण कार्य विभाग, बिहार पटना।

विषय :- शीर्ष MR(3054) ''नई अनुरक्षण नीति 2018'' योजनान्तर्गत पथ के निर्माण में संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में। महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण नीति 2018'' योजनान्तर्गत पथ:--

- 1. BARO BAZAR GARHARA
- 2. Begusrai jila antargat NH 31 se harpur muslim tola hote IOC harpur mokhay sadak isthit ashok saw ke ghar tak path nirman का Surface कार्य पूर्ण हो चुका है। इस कार्य के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अन्0:-यथोक्त।

विश्वासभाजन

ग्रामीण कार्य विभाग

कार्य प्रमंडल बेगुसराय

Office Of The Executive Engineer Works Division, Begusarai Rural Works Department

Requisition Format for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

2	-	No. P						
RM/BE/BEG/I 9/0010	RM/BE/BEG/1 9/0009	Package No.						
Begusrai jila antargat NH 31 se harpur muslim tola hote IOC harpur mokhay sadak isthit ashok saw ke ghar tak path nirman	BARO BAZAR - GARHARA 32010502020	Name of Road						
32010503005								
<u>3785</u> 04-09-2019								
0.45	2.15	Administrative Length Amount (in Km) (in Lakh)						
14.55	67.5	Administrative Length Amount (in Km) (in Lakh)						
9.107	Initial Rectification with Surface Renewal (in Lakh) 41.321							
4.12291	19.02746	Agreement Amount Initial 5 Year tification Routine 1 Surface Maintenance enewal (in Lakh)						
08-MBD/NMP- 2018/2020-21	08-MBD/NMP- 2018/2020-21	Agreement No. & Date						
04-Mar-22	04-Mar-22	Date of Actt Completion as per Agreement						
		ual Date of npletion						
3421	Actual Date Value of IRI of Bitumen of Gin mm/Km) Layer in mm 3242 SDBC-25mm							
SDBC-25mm	SDBC-25mm							
SDBC-5	SDBC-5	Value of Bitumen content in Percentage						
3.55980	16.13803	Value of Previous Up-to-date Requisition Bitumen Total Alloted Expenditure against content in Amount as per MIS work done Percentage (in Lakh) (in Lakh) (in Lakh)						
3.55980	16.13803	Up-to-date Requisition Expenditure against as per MIS work done (in Lakh) (in Lakh)						
5.33970	Requisition against work done (in Lakh)							
Surface Complete	Surface Complete	Remarks						

Divisional Account Officer Rural Works Department Works Division Begusarai

Executive Engineer

Work(s) Division Begusarai Rural Works Department

EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION, **BEGUSARAI**

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150) Form of Utilisation Certificate upto the month of August- 2021

Name of the Head :- New Maintenance Policy -2018 Under MR -3054 Month:- August-2021 (28.07.2021)

		Y		Trugust 2021 (2010/12021)
SI. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
l	2	4	5	6
1	Rural Roads Under New Maintenance Policy -2018 Under MR-3054	Up to letter no. 52 Encl Dtd. 24.08.2021	896.28682	Certified that out of Rs. 896.28682 Lacs received during the year 2020-21 in favour of Executive Engineer R.W.D. Works Division, Begusarai, Bihar a sum of Rs 893.63958 Lacs has been utilized for the purpose of New Maintenance Policy -2018 Under MR-3054 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 2.64724Lacs remaining unutilized at the end of the period under.
	Total -		896.28682	, , , , , , , , , , , , , , , , , , , ,

Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly 2 fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for witch it was Sanctioned.

Kind of Checks Exercised :-

- i. Works have been supervised by Executive Engineer/Superintending Engineer.
- ii.Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- iii. Construction materials have been tested.
- iv. Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- v. All other codal formatities have been observed.

Physical Progress achieved :-

- i. Construction of Road Works.
- ii. Construction of CD. Works.

Divisional Acdounts Officer Rural Works Department Works Division, BEGUSARAI

Executive Engineer Rural Works Department Works Division, BEGUSARAI

Name of Road - BARO BAZAR - GARHARA

Date	Time	Section	Length	Bumps	Speed	28	0	CATECOBY		
7							11/1	CALEGOAL	Latitude	Longitude
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD		
6/6/21	13: 52: 8	37	0.1	220	10.1	2200	3039	G	25.44203	85.991228
6/6/21	13: 52: 43	37	0.1	300	20.2	3000	3812	G	25.441898	85.99182
6/6/21	13: 52: 43	37	0.1	200	10.1	2000	2948	G	25.441898	85.99182
6/6/21	13: 53: 18	37	0.1	210	20.2	2100	2676	G	25.441898	85.99182
6/6/21	13: 53: 18	37	0.1	300	20.2	3000	3540	G	25.441898	85.99182
6/6/21	13: 53: 18	37	0.1	320	20.2	3200	3835	G	25.441898	85.99182
6/6/21	13: 53: 53	37	0.1	210	20.2	2100	2926	G	25.441898	85.99182
6/6/21	13: 53: 53	37	0.1	230	20.2	2300	3153	G	25.441898	85.99182
6/6/21	13: 53: 53	37	0.1	260	20.2	2600	3494	G	25.441898	85.99182
6/6/21	13: 54: 29	37	0.1	230	10.1	2300	3153	G	25.441898	85.99182
6/6/21	13: 54: 29	37	0.1	310	20.2	3100	3790	G	25.441898	85.99182
6/6/21	13: 55: 4	37	0.1	230	20.2	2300	.3017	G	25.441898	85.99182
6/6/21	13: 55: 4	37	0.1	210	10.1	2100	2926	G	25.441898	85.99182
6/6/21	13: 55: 39	37	0.1	240	20.2	2400	3130	G	25.441898	85.99182
6/6/21	13: 55: 39	37	0.1	220	20.2	2200	3039	G	25.441898	85.99182
6/6/21	13: 56: 15	37	0.1	240	20.2	2400	3130	G	25.441898	85.99182
6/6/21	13: 56: 15	37	0.1	140	10.1	1400	2130	G	25.441898	85.99182
6/6/21	13: 56: 50	37	0.1	200	20.2	2000	2812	G	25.441898	85.99182
6/6/21	13: 56: 50	37	0.1	390	20.2	3900	4698	Þ	25.441898	85.99182
6/6/21	13: 57: 25	37	0.1	250	20.2	2500	3108	G	25.441898	85.99182
6/6/21	13: 57: 25	37	0.1	330	20.2	3300	3881	G	25.441898	85.99182
6/6/21	13: 58: 0	37	0.1	250	20.2	2500	3108	G	25.441898	85.99182

RWD Works Division Executive Engineer Begusarai

* X ^ 2 + 1.136 * X + 132.5

3500

4108 URAL ROAD

Average Poor 4001-5000 >5001

0 0.1 0.2	1130	Mm/ 3130	4130 -	File :C.\Users\E Name of Custor	Print Generate Report and Graph		Section No. 37	0-40-20	b number 37	Name of Work BAPO BAZAR GARHARA	Name of Chanden Kuniar Customer:
0.3 0.4 0.5 0.6 0.7 0.8 0.9 1 1.1 Distance *1000 m				File :C:\Users\BRRDA37\Desktop\Chandan Kumar\06061359.Ms, Section No. :37, Eqn : Y = 0 * X ^ 2 + 1.13t Name of Customer :Chandan Kumar, Name of Work/ Road :BARO BAZAR - GARHARA Lab Job number :37	and Graph	End Location:	Start Location :	Weather	Start E No :	HARA Machine No: 414	Test Date : 06-06-2021 -
1.2 1.3 1.4 1.5 1.6 1.7 1.8 1.9 2 2.1 2.2			>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	ds. Section No. :37. Eqn.:Y=0*X^2+1.136*X+ ARO BAZAR - GARHARA. Lab Job number :37	Redraw Graph Map View	Equation : $Y = 0.4 \times .2 \times 1.136.4 \times .132.5$	Dist Range : 0 To 23 01 -1000 m	UIV Range: 1130 To 6000 1000 mm/km	Side : Interval	Road Type: (R) RURAL ROAD	Road Name: BARO BAZAR - GARHARA

Executive Engineer
RWD Works Division Begusarai