



कार्यपालक अभियंता का कार्यालय

ग्रामीण कार्य विभाग, कार्य प्रमंडल बेगुसराय



पत्रांक— १५०३५०
मो०—8986915365

दिनांक— ०३/०९/२०२१
ई मेल — ee.begusarai.rwd2@gmail.com

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेगुसराय ।

सेवा में,

नोडल पदाधिकारी,
नई अनुरक्षण नीति 2018" (3054-MR)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय :- शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ के निर्माण में संवेदक के विपत्र भुगतान हेतु राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के संबंध में सूचित करना है कि शीर्ष MR(3054) "नई अनुरक्षण नीति 2018" योजनान्तर्गत पथ:-

1. BARO BAZAR – GARHARA

2. Begusrai jila antargat NH 31 se harpur muslim tola hote IOC harpur mokhay sadak isthit ashok saw ke ghar tak path nirman का Surface कार्य पूर्ण हो चुका है। इस कार्य के भुगतान हेतु आवंटन की अधियाचना विहित प्रपत्र में भर कर की जाती है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अनु०:-यथोक्त।

विश्वासभाजन

[Signature]
३१/९/२१
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बेगुसराय

[Signature]
०३-९-२१

**Office Of The Executive Engineer
Rural Works Department
Works Division, Begusarai**

Requisition Form for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)

Sl. No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval(AA) Letter No. & Date	Administrative		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumen Layer in mm	Value of Bitumen content in Percentage	Previous Total Alloted Amount (in Lakh)	Up-to-date Expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in Km)	Amount (in Lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)										
1	RM/BE/BEC/I 9/0009	BARO BAZAR - GARHARA	32010502020	3785 04-09-2019	2.15	67.5	41.321	19.02746	08-MBD/NMP- 2018/2020-21	04-Mar-22		3242	SDBC-25mm	SDBC-5	16.13803	16.13803	24.20705	Surface Complete
2	RM/BE/BEC/I 9/0010	Begusarai jila antargat NH 31 se harpur muslim tola hote IOC harpur mukday sadak ishtit ashok saw ke ghar tak path nirman	32010503005		0.45	14.55	9.107	4.12291	08-MBD/NMP- 2018/2020-21	04-Mar-22		3421	SDBC-25mm	SDBC-5	3.55980	3.55980	5.33970	Surface Complete

Divisional Account Officer
Rural Works Department
Works Division Begusarai

[Signature]
03-09-21

Executive Engineer
Rural Works Department
Work(s) Division Begusarai

[Signature]
03-09-21

[Signature]
03-09-21

[Signature]
31/9/24

EXECUTIVE ENGINEER, RURAL WORKS DEPARTMENT, WORKS DIVISION,
BEGUSARAI

FROM GFR 19 - A

(See Government of India's Decision (I) below Rule - 150)

Form of Utilisation Certificate upto the month of August- 2021

Name of the Head :- New Maintenance Policy -2018 Under MR -3054 Month:- August-2021 (28.07.2021)

Sl. No.	Name of Scheme	Sanctioned No./ Date	Amount Received (in Lacs Rs.)	Particulars
1	2	4	5	6
1	Rural Roads Under New Maintenance Policy -2018 Under MR-3054	Up to letter no. 52 Encl Dtd. 24.08.2021	896.28682	Certified that out of Rs. 896.28682 Lacs received during the year 2020-21 in favour of Executive Engineer R.W.D. Works Division, Begusarai, Bihar a sum of Rs 893.63958 Lacs has been utilized for the purpose of New Maintenance Policy -2018 Under MR-3054 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 2.64724 Lacs remaining unutilized at the end of the period under.
	Total -		896.28682	


- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was Sanctioned.


Kind of Checks Exercised :-


- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test checks conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road Works.
- Construction of CD. Works.


Divisional Accounts Officer
Rural Works Department
Works Division, BEGUSARAI


Executive Engineer
Rural Works Department
Works Division, BEGUSARAI


03-09-21

Name of Road - Begusrai jila antargat NH 31 se harpur muslim tola hote IOC harpur mokhay sadak

isthit ashok saw ke ghar tak path nirman

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY ROAD	Latitude	Longitude	Event	
6/6/21	14:52:8	38	0.1	300	10.1	3000	3812	G	25.439877	86.70707	Normal	$Y = 0 * X^2 + 1.136 * X + 132.5$
6/6/21	14:52:44	38	0.1	220	10.1	2200	3039	G	25.439877	86.70707	Normal	$X = 5100$
6/6/21	14:53:19	38	0.1	240	10.1	2400	3402	G	25.439877	86.70707	Normal	$Y = 5926$
6/6/21	14:53:54	38	0.1	310	10.1	3100	3926	G	25.439877	86.70707	Normal	(R) RURAL ROAD
6/6/21	14:53:54	38	0.1	210	10.1	2100	2926	G	25.439877	86.70707	Normal	Good Average Poor <4000 4001-5000 >5001

[Signature]
15/9/21

[Signature]
Executive Engineer
RWD Works Division
Begusarai

Name of Customer : Chandan Kumar
 Name of Work/ Road : Begusarai jila antargat NH 31 se
 Lab Job number : 38
 Date : 06-06-2021
 Section No. : 38


Test Date : 06-06-2021
 Road Name : Begusarai jila antargat NH 31 se
 Machine No : 414
 Road Type : (R) RURAL ROAD
 Start S No :
 Side :
 Interval :
 Weather :
 UIV Range : 1926 To 5000 mm/km
 Start Location :
 Dist Range : 0 To 0.6 0.1 * 1000 m
 End Location :
 Equation : test

Print Generate Report and Graph

File : C:\Users\BRDDA3\Desktop\Chandan Kumar\06061455.Xls. Section No. : 38. Eqn. test
 Name of Customer : Chandan Kumar. Name of Work/ Road : Begusarai jila antargat NH 31 se harpur muslim tola hote

Redraw Graph

Map View



Signature
 13/9/21

Executive Engineer

RWD Works Division Begusarai