

Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs Executive Engineer RWD Div. - Muzaffarpur East-01
2 Name of Block/Road - Muzaul - T05 to Malpur Agsai

A For Road

- 1 Damage Location/Chainage 0+650M
2 Damage Length — 650M
3 Nature of Damage Crest and Embankment
4 Details of Restoration Works

- i Material being used in Restoration Works — Bricks Bats — 906.19 M³
ii Equipments/Tools being used in Restoration Works — Tractor, JCB and Roller
iii Procedure Taken up in Restoration Works Tipper
iv Restored Length — 650M Completed.

B For Bridge

- 1 Damage Location/Chainage
2 Damage Length
3 Nature of Damage
4 Details of Restoration Works

- i Material being used in Restoration Works
ii Equipments/Tools being used in Restoration Works
iii Procedure Taken up in Restoration Works
iv Restored Length

NA

§ Satisfactory

Shankar
24.11.24
Signature of JE/AE/EE

AE
24.11.24
AE.

R. W. D.
24.11.24
Executive Engineer
R. W. D. Works Division, Mahanar

GENERAL ABSTRACT

Name of the Road :-
District
Block
Division

T05 TO MALPUR AGRAIL
Muzaffarpur
Muraul
Muzaffarpur East-1

5.045 KM

Length of Road (in Km)

No.	DESCRIPTION	AMOUNT (LAKHS)
1	Brick Bat	19.584
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	19.584
TOTAL COST OF PROJECT IN LACS =		19.584

18.71

18.71

[Signature]
2.11.21

JE
RWD

[Signature]
02.11.21

AE
RWD

[Signature]
24.11.21

EE
RWD

As Per S.E. RWD (M) Circle Muz.
Letter No 1179 Dated 01/10/2021
Estimate has been verified by inspecting
E.E. RWD. (M) Division *Hakim*

Technically Sanctioned for Rs. 18.71 lacs
(Rs. Eighteen lacs seventy one thousand) only
(provisionally)

[Signature]
24.12.21
Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpur