

Inspection Report for Flood Damage Work

Date:- 15.09.2021

Name of PIU- RWD WORKS DIVISION, SRSAPAM-3

Name of Block/Road- L 113 SreeSagar-Raipurchase (Chenai Road)
Road to Chotaker Kuar (VP 93)

(A) For Road-

^{Damage}
1. Damage location/Chainage :- 1050m

2. Damage Length :- 33 m

3. Nature of Damage :- Shoulder of RT

4. Details of Restoration Works:-

(i) Material being used in Restoration Works:- Brick bat

(ii) Equipment's/Tools Being used in Restoration Works:- JCB, Hydra

(iii) Procedure taken up in Restoration works:- Backfilling

(iv) Restored Length :- 33 m

(B) For Bridge:

1. Damage location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works:-

(i) Material being used in Restoration Works:-

(ii) Equipment's/Tools Being used in Restoration Works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length :-


15.09.21

Signature of JE


15/09/21

Signature of AE

Signature

EE Sasan 2

(Name of Inspection)



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

77:5 copy
08.12.21

YEAR-2021-22

By SE

DETAILED PROJECT REPORT FOR MOTORABLE WORK

बिहार



DISTRICT :-	Rohtas	BLOCK :-	Chenari
ROAD NAME :	L113 Sheosagar - Raipurchore (Chenari Road) road to Chhotak Kenar VR93		
HEAD	F.D.R.	YEAR-2021-22	
TOTAL LENGTH OF ROAD	:	2805.000	KM
Damaged Length	:	40.000	M
TOTAL COST OF PROJECT	:	1.099	LAKH

Executive Engineer
RWD Sasaram-1

Technically sanctioned for Rs 1,09,900 = 10 (Lacs)
One lac nine thousand nine hundred 00

12/11/21

आधीश्वर उम्पियल

मुम्बई काय विभाग

काय अंचल, सासाराम

12/11/21