

Schedule ^{FD R} XLV-Form No. 134

MS. No - 62

year - 2021-22

मिलिका मया फेला फो

मलिका मया फेला फो

DIVISION

SUB-DIVISION

मलिका - धर्म दक्ष

Measurement Book

Dhamdaha DIVISION

Dhamdaha SUB-DIVISION

mulliyar Maye tola to mulliyar
main road

MEASUREMENT BOOK

No. - 62

प्रमाणित किताब है कि इस माप
पुस्तक में 'मुद्रित' है 50 पन्ने हैं यह
माप पुस्तक अहमदाबाद पब्लिकेशन
अहमदाबाद 5 तह किताब डिपार्टमेंट

Name of Officer

Date of first entry

Executive Engineer

Date of last entry

Rural Works Department

Works Division, Dhamdaha (Pune)

05/10/21

Name to work— 1
 Situation of work—
 Agency by which work is executed—
 Date of measurement—
 No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
NAME of WORK: I.D.P.					
(Mainable & Restoration of Road Milkya Nya Tola to Milkya main Road.					
Agency:-					
(RECORD-ENTRY)					
1/1 Construction of embankment from Borrow Pits					
(a) 4 M X (1.15 + 0.75) M X 45					
		2			

$$\frac{4 \times (0.45 + 0.35) \times 45}{2} = 1.52 \text{ m}^3$$

$$(b) \text{ Edge - } 3.20 \text{ M} \times \frac{(1.15 + 0.75) \times 45}{2}$$

$$\times \frac{(0.45 + 0.35) \times 45}{2} = 1.22 \text{ m}^3$$

$$\text{Total} = 2.74 \text{ m}^3$$

2 - Providing Brick ball including spreading and laying.

$$(a) 4 \text{ M} \times (3.4 + 1.5) \times \frac{(1.85 + 1.75) \times 45}{2}$$

$$\text{(Full)} = 17.64 \text{ m}^3$$

Continuation

28-10
Executive Director
Rural Works Department
Work Division Chandraha (Punjab)

Scanned with CamScanner

Particulars	Details of actual measurement				Contents of area
	No	L	B	D	
NAME of work: J. D. P. Montabla & Restoration of Road Milkya Naya Tolna To Milkya main Road.					
Agency:-					
ABSTRACT OF COST/					
1/1 construction of					
embankment from					
Bottom of Pith Lead					
up to 1000 mtr					
2.74 M ³ Qty vide on					
P-01 Item No (01)					
@ Rs - 171203/m ³					
					Rs - 46920

2/2 Providing Brick ball				
including, spreading				
and Laying 46.82				
m ³ Qty vide on P-02				
Item No - (02) @				
Rs 2188 = 35/m ³				

				Rs. 102450
				Rs. 10292820
Add 12% C.S.T	(+)			1235120
Add 1% Labour cell	(+)			102520
Add S. Fee	(+)			490020
				Rs - 12120420
Rs. 1,21,20420				

Prepared	23-12-2021	23/12/2021		
(J.E.)		A.E.		23.12.21

Continuation

E-E

Date:- 04-12-2021

Inspection Report for flood damage work

(Year 2020-22)

1. Name of PIUs- DHAMDANA

2. Name of Block/Road- DHAMDANA

A. For Road - MILKIYA NAYA TOLA TO MILKIYA MAIN ROAD

1. Damage Location/Chainage : AT CH -
2. Damage Length : 9.0 Mtr
3. Nature of Damage :
4. Details of Restoration :

i Material being used in Restoration : Earthwork, Brick bats
ii Equipment/Tools being used in Restoration works :
iii Procedure taken up in Restoration works :
iv Restored Length : - Ch 9.0 Mtr.

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
i Material being used in Restoration :
ii Equipment/Tools being used in Restoration works :
iii Procedure taken up in Restoration works :
iv Restored Length :

P. Kumar
04-12-21
Signature of JE/AE/EE

P. Kumar
04/12/2021
A.E.

P. Kumar
04-12-21
Executive Engineer
Rural Works Department
Works Division Dhamsana (Purnea)

M. S.
04/12/21
Signature
Executive Engineer
(Name of Executive Engineer)
Works Division Dhamsana (Purnea)

Scanned with CamScanner

Scanned by CamScanner

Scanned with CamScanner