

Inspection Report for Flood Damage Works:-

Date :-

1. Name of PIUs – Executive Engineer, RWD, Raxaul:...
2. Name of Block – Ramgashwa
3. Name of Road – Ramgashwa - Subhramrey

(A) For Road

1. Damage Location/Chainage :- 750-794, 1433-1593, 2775-2780, 3050-3060
2. Damage Length :- 211 M
3. Nature of Damage:- Road crust damaged near Pond. one slab
culvert deck Slab also damaged.
4. Details of Restoration Works:- Brick Bats filling
 - (i) Material being used in Restoration works: Brick Bats
 - (ii) Equipments/ Tools being used in Restoration works: Tractor
 - (iii) Procedure taken up in Restoration works: Departmental.

(iv) Restored Length: 211 M

Satisfactory

19/04/22
J.E

19/04/22
m

15/2/22
Executive Engineer
RWD, (W) Div. Raxaul:...

Name of Work:-

Estimate for Repair of Road breaches (Damaged by Flood) for
Sukhlsemra (BR-11R-039) For year 202

ngarhwa -

Head - FDR

Length-5.60KM

Sl No.	Item No.	Name of Item	unit	No	Length	Width	Height	Qty.	Rate	Amount
1		Labour for laying dry graded Jhama Khoa or stone filter under Brick Pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I.	cum	As Per	Appendix			826.000 353.16	2027.60 1911.02	1269440.00 716067.00 674892.00
TOTAL (in Re.)									1269440.00	

Say Rs

1269440.00

716067.00
674980.00

[Signature]
30/10/21

Junior Engineer,
Rural Works Department,
Works Section, Ramgarhwa

[Signature]
30/10/21

Assistant Engineer,
Rural Works Department,
Works Sub Division, Ramgarhwa

[Signature]
30/10/21
Executive Engineer,
Rural Works Department,
Works Division, Raxaul

For factor A.T S is accorded for Rs. 6,74,900.00 W
(.....crore.....Six.....lacs.....seventy four
.....hundred.....thousand
.....only.

[Signature]
18/03/2022
S.E. (R.W.D.)
works Circle
Motihari