

Inspection Report of Flood Damage work

Name of PIUs:- RWD Works Division, Darbhanga Inspected by Benibury.
Name of Block/Road:- chmn^o ke Nikat to Salha. [BAHERA]

A. For Road

1. Damage Location Chainage:- 0 to 1 km
2. Damage Length :- 0.256 km
3. Nature of Damage :- Road Surface damage
4. Details of Restoration Works

- i. Material being used in Restoration works:- Buick Bats
- ii. Equipment's /Tools being used in Restoration works:- JCB/Tractor, Labour
- iii. Procedure taken up in Restoration works:- Laying of Buick Bat with
- iv. Restored Length:- 0.256 km Light Ramping.

B. For Bridge

1. Damage Location Chainage:-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works
- i. Material being used in Restoration works:-
- ii. Equipment's /Tools being used in Restoration works:-
- iii. Procedure taken up in Restoration works:-
- iv. Restored Length:-
- } N/A

work found satisfactory.

Signature of JE/AE/EE

Charvi
10/3/21
AE

Signature

(Name of Inspection)

FDR

DISTRICT :-	DARBHANGA	
BLOCK :-	BAHERI	
Name of Raad :-	Chimni Ke Nikat to Salha.	
	Length of the Road:-	2.660 KM.
	Effective Length	0.256 KM.

GENERAL ABSTRACT OF COST

Sl No.	Item of Work				Amount	
					(in Rs.)	
1	Cost for restoration				243809.15	3,03,037.17
2	Add 12 % GST				29257.09	36,364.46
3	Add 1 % Labour Cess				2438.09	3,030.37
4	Seigniorage Fee	Quantity (in cum)	Rate (in Rs.)	%		
	(Br. Bats) in cum 121.603	151.144	1032.00	10.00	12549.43	15,598.04
Total cost:-					288053.76	3,58,030.04
Say Rs.					288054=00	3,58,030.00

[Signature]
06.11.2024
Junior Engineer
Baheri

[Signature]
Assistant Engineer
Baheri

[Signature]
Executive Engineer
R.W.D.(W) Division, Darbhanga-1

कार्यपालक कमिशनर अर्वाइज्ड डि राउन्ड चारिटेबल डि आन्युइटी
Technically sanctioned for Rs 288054 200/2
Two lacs Eighty Eight thousand fifty four only

[Signature]
Superintending Engineer
RWD, Works Circle, Darbhanga
4/15/22

