

थामीण कार्य विभाग

Rural Works Department, Govt of Bihar

DETAILD PROJECT REPORT FOR MOTRABLE REPAIRING OF ROAD

F.D.R. PART - MOTRABLE RESTORATION

L076- T02 TO BISARE (DIVERSION)

DETAILED ESTIMATE OF F.D.R. MOTRABLEREPAIRING ROAD

ROAD LENGTH	0 TO 170	63
DISTRICT	KATIHAR	
BLOCK	PRANPUR	
DIVISION	MANIHARI	
TOTAL LENGTH OF ROAD	1.763	KM
TOTAL COST OF F.D.R. PART - A	Rs. 25.737	Lacs
ADD G.S.T @ 12%	Rs. 3.088	Lacs
ADD Labour Cess @ 1%	Rs. 0.257	Lacs
ADD Seigniorage Fee @ 10%	Rs. 1.401	Lacs
TOTAL COST OF RESTORATION WORK In Rs.	Rs. 30.483	Lacs

SUBMITTED BY

The Executive Engineer, Works Division, Manihari

प्रतिवेदन

प्रस्तुत प्राक्कलन ग्रामीण कार्य विभाग कार्य प्रमण्डल मिनि हारी अन्तर्गत . प्राणिप रे ह पथ 1076- 702 से विसारे (.....) जो भागीय Online Morititring System MIS पर अपलोड है के बाढ 2021 से क्षतिग्रस्त हो जाने के कारण यातायात लायक Moterable हेतु बनाया गया है। इस कार्य को करने का निर्देश ग्रामीण कार्य विभाग, बिहार सरकार के पत्रांक:-मु0अ0-4(मु0) विविध (कार्य) -23-291/2019-4275/पटना, दिनांक-22/10/2021 से प्राप्त है। इस पत्र से Real time Geotagged Photographs को कार्य के दौरान अपलोड करते हुए (Moterable) कार्य कराना सुनिश्चित करने का निर्देश प्राप्त है। उक्त निर्देश के आलोक में १०२१..... अतिवृष्टि / बाढ़ उपधार से आए बाढ के करण इस पथ के रोडवे के क्षतिग्रस्त हो जाने से सुरक्षित आवागमन हेतु Moterable कार्य कराया गया है। MIS में निकलनेवाली इस नदी के तेज धार से इस पथ में कटाव की स्थिति बनी। मोटरेबल कार्य में आवश्यकतानुसार मिट्टी भराई, लोकल बालु भराई, खाली सिमेंट बैग में लोकल बालु भरकर, बॉस का पाइल, चचरी, बॉस का रनर, ह्यूम पाइप एवं ब्रिक बैट का इस्तेमाल किया गया है । निर्देशानुसार कराए गए कार्य कि Geotagged Photographs Real Time के साथ MIS पर उद्वत है। MIS की छायाप्रति, अपलोडेड फोटोग्राफ की छायाप्रति, दर विश्लेषण एवं विभागीय आदेशों की छायाप्रति प्राक्कलन में संलग्न की जा रही है। प्राक्कलन में प्रयुक्त दर अद्यतन है।

प्राक्कलन की यथाशीध्र अनुमोदन अपेक्षित है ताकि अग्रेतर कार्रवाई की जा सके।

कनीय अभियंता ग्रामीण कार्य विभाग कार्य प्रशाखा, प्राणा ५

Sarx 20/11/24 सहायक अभियंता ग्रामीण कार्य विभाग ग्रामीण कार्य विभाग ग्रामाण कार्य विभाग कार्य अवर प्रमंडल, जार्य प्रमंडल, जार्य प्रमंडल, जार्य प्रमंडल,

Date: 1. Name of PIUs- 2. Name of Block/Road- Prampur, Lo76-Tor to Bigare A. For Road
1. Damage Location/Chainage: (H — I-okm. 2. Damage Lengh: 127 m 3. Nature of Damage: washowf 6. 4. Details of Restoration: Bricks bary flying if Material being used in Restoration works: iii Procedure taken up in Restoration works: iii Procedure taken up in Restoration works: iv Restored Length
B. For Bridge 1.Damage Location/Chainage: 2. Damage Lengh 3.Nature of Damage 4.Details of Restoration i Material being used in Restoration ii Equipment/Tools being used in Restoration works: iii Procedure taken up in Restoration works iv Restored Length : 127 m
Signature of JE/AE/EE Signature (Name of Inspector)

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD:

L076- T02 TO BISARE (DIVERSION)

DISTRICT

KATIHAR

DIVISION

MANIHARI

BLOCK

PRANPUR

LENGTH OF ROAD (IN KM)

1.763

SI. No.	ITEM OF WORK	AMOUNT (LAKHS)
1	EARTH WORK	0.000
2	HUME PIPE	0.000
3	BRIKCK BAT	25.737
4	SAND BAGS	0.000
5	BAMBOO WORK	0.000
6	STEEL DRUM SHEET	0.000
	TOTAL COST OF PROJECT =	25.737
	Add G.S.T. @ 12%	3.088
	Add Labour Cess @ 1%	0.257
	Add Seigniorage Fee @ 10%	1.401
	Total Cost of Restoration Work =	30.483

J.E. RWD

A.E.

RWD

B.E.

Technically Sanction for Rs 30.483 lace Rupees
therety laces fourty eight thousand three
Hundred Joney.

Superintendent Engineer Rural Works Department Works Circle, Purnea