

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बेनीपट्टी।

पत्रांक..... 1397

दिनांक 30.07.22

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह- सचिव,
बिहार ग्रामीण पथ विकास अभिकरण,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:- शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) में आवंटन उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में कहना है शीर्ष NEW MAINTENANCE POLICY - 2018 (MR - 3054) अन्तर्गत पथ में संलग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाय ताक संवेदक का भुगतान किया जा सके।

अनु०:-

1. अधियाचना प्रमाण पत्र 1 पृष्ठ में।
2. उपयोगिता प्रमाण पत्र एक प्रति।

विश्वासभाजु


कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, बेनीपट्टी।

FORM GFR 19-A

(See Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate Upto the month of 30 June 2022

New Maintenance policy - 2018

PIU – Executive Engineer, R.W.D (W) Division, Benipatti

SL. No	Name of Gen.heme	Sanction No. & Date with Amount (In Rs. lacs)	Amount Received (In Rs. lacs)	Particulars
1	Construction of Rural roads under New maintenance policy - 2018	Authorization letter No. 03 we dt- 08.06.2022 Rs.46.55787	964.68887	Certified that out of Rs.964.68887 Lakh received during the years up to 2022-23 (30 June 2022) in favour of Ex. Engineer, RWD (W) Division Benipatti, Madhubani, Bihar, a sum of Rs. 917.52254 Lakh has been utilized for the purpose of New maintenance policy-2018 as given in the margin for which the balance of Rs 47.16633 Lakh remaining unutilized at the end of the period under.


2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD Works.


Divisional Account Officer,
R.W.D (W) Division
Benipatti


Executive Engineer
R.W.D (W) Division
Benipatti

Formate of Requisition under Head New Maintenance policy - 2018 (MR- 3054) for the month of July- 2022

Division :- Benipatti

Sl. No.	Package No.	Name of road	Project ID as per MTS	Administrative Approval (AA) Letter No & Date		Administrative Approval (AA)		Agreement Amount (in Lakh)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RL (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (in Lakh)	up-to-date expenditure as per MTS (in Lakh)	Requisition against work done (in Lakh)	Remarks
				Length (in km)	Amount of (in lakh)	Initial Rectification with Surface Renewal (in Lakh)	5 Year Routine Maintenance (in Lakh)												
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	MIR-N/19-20 Benipatti/04	Chahuta to Sahdullahpur	31910002027	1859/ 24.06.2019	4.990	173.24500	103.24484	45.16681	67MIBD/20-21 26.11.2020	25.11.2021	—	—	2116	25	5	0.00	0.00	78.55101	BT Work Completed
Total										—	—	—	2116	25	5	0.000000	0.000000	78.55101	

Divisional Account Officer,
R.W.D(W)/Div. Benipatti

Executive Engineer,
R.W.D(W)/Div. Benipatti


22	11:36:0	32	0.1	170	10.1	1700	1667 G	26.32876	85.4005	Normal
25/7/22	11:36:2	32	0.1	280	10.1	2800	2755 G	26.32942	85.40555	Curve
25/7/22	11:36:37	32	0.1	220	10.1	2200	2162 G	26.32988	85.41328	Normal
25/7/22	11:36:37	32	0.1	120	20.2	1200	1173 G	26.33068	85.41885	Normal
25/7/22	11:37:12	32	0.1	120	20.2	1200	1173 G	26.33132	85.42608	Normal
25/7/22	11:37:12	32	0.1	170	10.1	1700	1667 G	26.33181	85.4345	Normal
25/7/22	11:37:12	32	0.1	230	10.1	2300	2261 G	26.33226	85.44343	Normal
25/7/22	11:37:47	32	0.1	250	20.2	2500	2458 G	26.33271	85.45202	Normal
25/7/22	11:38:0	32	0.1	260	20.2	2600	2557 G	26.33337	85.46027	Normal
25/7/22	11:38:0	32	0.1	310	20.2	3100	3052 G	26.33399	85.4668	Normal
25/7/22	11:38:23	32	0.1	230	20.2	2300	2261 G	26.33461	85.47423	Normal
25/7/22	11:38:23	32	0.1	300	20.2	3000	2953 G	26.3352	85.48198	Normal
25/7/22	11:39:0	32	0.1	230	20.2	2300	2261 G	26.33583	85.4904	Normal
25/7/22	11:39:0	32	0.1	170	10.1	1700	1667 G	26.33642	85.49813	Normal
25/7/22	11:39:0	32	0.1	230	10.1	2300	2261 G	26.33699	85.50588	Normal
Avg							2116.22			

45
 275
 26/7/22
 RR

25-7-22
 AB

25-7-22
 2.0

File : C:\Users\RWD\OneDrive\Desktop\Om Const\26081149.Xls, Section No. : 32, Eqn : $Y = 0 * X^2 + 0.989 * X -$
 Name of Customer : M/S Om Construction Prop Om Namo Narayan, Name of Work/ Road : Chahuta - Sahdullahpur.



Y
2023/07/28
28/7/22
R.R.

25.7.22
AB

25-7-22
Z.C

(These four lines should be repeated at the commencement of the measurement relating to each work)

Continuation

[illegible]

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
④ providing & laying w.b.c. grade III etc.					
Qty vide T.M.B.P. No. ⑤					
= 99.73 M ³ @ 4066 = 15/M ³					
					R 4,45,513=
⑤ providing & applying Prime coat S.S. etc.					
Qty vide T.M.B.P. No. ⑥					
21342.73 M ² @ 41 = 21/M ²					
					R 55,3342=
⑥ providing & laying Mix					
Scal surface 20 mm thick					
Qty vide T.M.B.P. No. ⑬					
= 3766.84 M ² Limit = 3766.39 M ²					
@ 213 = 71/M ²					R 8,04,915=
⑦ providing and applying tack coat RS+ etc.					
Qty vide T.M.B.P. No. ⑭ = 3766.84					
" " " ⑮ = 18781.25					
" " " = 22518.09 M ²					
@ R 13 = 98/M ²					R 3,15,222=
⑧ providing & laying S.B.S.D.B.C. 25 mm thick etc.					
Qty vide T.M.B.P. No. ⑰					
= 469.535 M ³ @ 19737 = 55					
					R 50,41,656=

Continuation

Continuation