

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक-.....1767...../बक्सर

दिनांक-...31/12/22.....

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 सरम्मति (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन

 07.12.22

कार्यपालक अभियंता
ग्रा०का०वि०, कार्य प्रमंडल- बक्सर

 07/12/22

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Dec 2018

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Constructi on of Rural Roads under MR (3054) Maintena nce	Lt. No.- 05, dt.-25.01.2022	5641.41491	Certified that out of Rs. 5641.41491 lacs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 5630.56661 lacs been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs 10.84830 lacs remaining unutilized at the end of the period under.
Total -				

2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 **Physical Progress achieved :-**

- Construction of Road works
- Construction of CD works

07.12.22
Executive Engineer
R.W.D. (w) Div. Buxar
AK
07/12/22

Requisition Form for Scheme Head- NRI (305-1) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Name of Road	Project ID as per MTS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Value of DN (in Rs.)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total expenditure incurred in per LKS (in Lakh)	Up to date expenditure against work done (in Lakh)	Requirements against work done (in Lakh)	Remarks
				Length (in Km)	Amount (in Lakh)	Initial Rectification With Surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)									
1	Road No. BU-44 to Village Dabhera, Dist. Buxar	10401901040	Lt. No. - 2006, Dt. - 02/05/2022	2.185	69.29	50.0314	20.1049	083/BD/2022-23 Dt. 15.11.2022	14.08.2023	2896	25 mm	5.03%	0	0	50.631.58	
2	Road No. BU-44 to Village Dabhera, Dist. Buxar	10401902007	Lt. No. - 2006, Dt. - 02/05/2022	1.5	54.017	45.15525	18.0089	083/BD/2022-23 Dt. 15.11.2022	14.08.2023	2845	25 mm	5.01%	0	0	45.114.58	

1. Signed Head Copy and Sub Copy (as copy) of recorded DA is attached

2. Up-to-date Physical Progress Report has been uploaded in JGIS

Executive Engineer
RWD (W), Dist. Buxar


194
21/12/22


कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर

का0आ0स.....¹⁷⁶⁸ बक्सर/ दिनांक...^{7/12/22}.....


कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत NH-84 to village Dahiwar via Dalsagar Tiwaripur पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत एवं कनीय अभियंता के द्वारा शत प्रतिशत किया गया है।


कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा बक्सर


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File : C:\Users\JAI MATA D\Downloads\SEC 55 REPORT -xlsx Section No. : 70, Eqn : test
Name of Customer : Shailesh Singh, Name of Work/ Road : NH 84 Village Dahiwar via Dalsagar Tiwaripur, Lab Job



26/6/14 JL

NAME OF ROAD:-NH84 TO VILLAGE DAHIWAR VIA DALSAGAR VIA TIWARIPUR CONTRACTOR NAME:-SHAILESH SINGH

Date	Time	Section	No.	In km	Length	Bumps	Rate	Speed	OR	IRI, TEGORY	Latitude	ongitude	Event
05/12/22	10:34:4	70	0.1	290	0	2900	2879 G	25.57986	84.04589	Speed Bre	X = 700		
05/12/22	10:34:39	70	0.1	310	30.3	3100	3039 G	25.5799	84.04588	Speed Bre	Y = 877		
05/12/22	10:35:14	70	0.1	250	30.3	2500	2498 G	25.58085	84.04598	Normal			
05/12/22	10:35:50	70	0.1	350	31.2	3500	3399 G	25.58184	84.04604	Speed Breaker			
05/12/22	10:36:0	70	0.1	360	30.3	3600	2596 G	25.58239	84.04656	Culvert	(R) RURAL ROAD		
05/12/22	10:36:25	70	0.1	270	30.3	2700	2679 G	25.58298	84.04071	Normal	Good	Average	Poor
05/12/22	10:37:0	70	0.1	280	31.2	2800	2769 G	25.58422	84.04923	Culvert	<4000	4001-5000	>5001
05/12/22	10:37:35	70	0.1	300	30.3	3000	2949 G	25.58508	84.0501	Normal	IRI VALUE=2812		
05/12/22	10:38:11	70	0.1	310	30.3	3100	3039 G	25.58547	84.05043	Culvert	MACHINE ID=315		
05/12/22	10:38:46	70	0.1	320	31.2	3200	2896 G	25.58565	84.05127	Normal			
05/12/22	10:39:0	70	0.1	230	30.3	2300	2318 G	25.58666	84.05194	Speed Breaker			
05/12/22	10:39:0	70	0.1	310	30.3	3100	3039 G	25.58769	84.05234	Normal			
05/12/22	10:39:21	70	0.1	300	31.2	3000	2949 G	25.58932	84.05297	Normal			
05/12/22	10:39:21	70	0.1	280	32.5	2800	2769 G	25.59013	84.05311	Normal			
05/12/22	10:40:0	70	0.1	250	30.3	2500	2498 G	25.591	84.05328	Curve			
05/12/22	10:40:0	70	0.1	330	31.2	3300	3219 G	25.5921	84.05346	Normal			
05/12/22	10:40:32	70	0.1	320	30.3	3200	2756 G	25.59286	84.05365	Normal			
05/12/22	10:40:32	70	0.1	250	30.3	2500	2498 G	25.59277	84.05363	Normal			
05/12/22	10:40:32	70	0.1	270	30.3	2700	2679 G	25.59515	84.05382	Culvert			
05/12/22	10:40:32	70	0.1	270	30.3	2700	2679 G	25.59515	84.05382	Normal			
05/12/22	10:40:32	70	0.1	290	31.2	2900	2859 G	25.59479	84.05426	Normal			
05/12/22	10:40:32	70	0.065	290	31.2	2900	2859 G	25.59482	84.0545	Normal			

20/12/22
28/12/22
25

$$Y = 0 * X^2 + 0.901 * X + 246.4$$