

कार्यपालक अभियंता, ग्रामीण कार्य विभाग कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 133 अतु

दलसिंहसराय / दिनांक 25/01/2022

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
सचिव-सह-प्राधिकृत पदाधिकारी
ग्रामीण पथ विकास एजेंसी पटना ।

विषय- **New Maintenance Policy 2018(MR New)** योजनान्तर्गत पथ में आवंटन
उपलब्ध कराने के संबंध में।


महाशय,

उपरोक्त विषय के संबंध में कहना है कि **New Maintenance Policy 2018(MR New)** योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान हेतु **Rs.-1.47901(One Lakh Forty Seven Thousand Nine Hundred One Rupess)** की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन **Rs.-1.47901(One Lakh Forty Seven Thousand Nine Hundred One Rupess)** उपलब्ध कराने की कृपा की जाये।

- अनु0- 1) अधियाचना प्रपत्र।
2) 19 ए फ़ॉर्म।
3) IRI Report की छायाप्रति सलग्न।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

Rural Works Department, Works Division Dalsinghsarai

Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018 (Initial Rectification and Surface Renewal)

Name of Division : PIU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA)	Agreement Amount (in Lac)	Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allocated Amount (Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks									
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19						
1	RRM/SA/DAL/19/006			1855/ 24.06.2019		66 MBD/2019-20 21.01.2020		16/09/2020		16/09/2020		3740		25mm		5.10%		98.39603		95.76139		1.47901		
		Dalsingarai Paetia Road - Gangauli	NEA22000531	5.500	172.260	91.251	48.051																	
		REO ROAD - BAHILAMPUR KHAM	NEA22000534	6.300	206.993	100.50100	55.984																	
				11.800	379.253	191.752	104.035																	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS.

[Signature]
Sr. Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

[Signature]
Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

FORM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto JANUARY 2022

New Maintenance Policy 2018(MR New)

PIU;- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	1787.50405	1787.50405	Certified that out of Rs-1787.50405 Lakh received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-1777.88419 Lakh has been utilized for the New Maintenance Policy 2018(MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-9.61986 Lakh remaining unutilized at the end of period under the time of completion
		1787.50405	1787.50405	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-


- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works


Sr.DAO

Rural Works Department,
Works Division Dalsinghsarai


Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

NY 1158648-28102

Schedule XLV-Form No.-134

DIVISION Feb Received A-512 2150 25 2151E

SUB-DIVISION

Accepted

MEASUREMENT BOOK

$$\begin{array}{r} 299 \text{ a.s. } 614 \text{ E.S. } 1131 \text{ D. } 851 \text{ D.} \\ \hline \end{array}$$

1

Name of Work -
 Situation of work -
 Agency by which work is executed -
 Date of measurement -
 No. and date of agreement -
 (These four lines should be repeated at the commencement
 of the measurements relating to each work).

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/10 -	Maintenance of road				
	from R.E.O road to				
	Balambar Khambar				
	under M.A. 3054				
Agency -	Sona Impacon				
	Pvt. Ltd.				
Agreement No -	66 MBD / 19-20				
Date of commencement -	17-12-19				
Date of Comp. (199) -	16-09-2020				
A.V. -	Est	10050119.			
	Mail	5693573.			
dt.	15-12-2020				
	15-10-2020				
①	PIV and fixing Lego of				
	Maintenance Project - 1				
	Maintenance Project - 1				
				2	
②	clearing and grubbing d.s.				
	and d.s.				
	2x	50x	30x	1.0	= 3000.00
	2x	60x	30x	1.0	= 3600.00
	2x	60x	30x	1.0	= 3600.00
	2x	7x	30x	1.0	= 420.00
					10620.00

Continuation

1.06 Ha


Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Item No (15) Provision of lapping former coal - CN					
Quantity wide TMB pyc					
No - 8 - 2157.33 m ² @					
Rs 40.32/m ² Rs				87817.00	
Item No (17) PIN M.S.B					
TMB pyc No - 8 -					
2157.33 m ² @ Rs					
191.16/m ² Rs				41243.00	
Item No (18) PIN tack					
Coal TMB pyc No -					
8 - 26012.55 m ² @					
Rs 13.84/m ² Rs				360014.00	
Item No (19) PIN S.D.B.C					
TMB pyc No. 03 -					
591.54 m ² @ Rs 9563.28/					
ms Rs				5704879.00	
Item No (20) PIN ad fine					
MM Cys large sand - 0					
Quantity wide TMB					
pyc No - 9 - 200 2.00 m ²					
@ Rs 112 (2.56/m ² Rs)				22525.00	
Rs =				9820559.00	
Add 13% GST + labor Rs				1276672.00	
=				11097226.00	
Cess 10% of Rs (-) Rs				1109722.00	
=				9987504.00	
Cess 1st + 2nd + 3rd (20%) (-) Rs				998750.40	
=				9576139.00	
=				411365.00	

21.01.2022
Continuation


22/1/22
AE

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय
नयी अनुरक्षण नीति 2018 के अध्याचना हेतु प्रमाण पत्र

क्र० स०	शर्त	अभियुक्ति
1	मापि पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है ।	REO ROAD - BAHLAMPUR KHAM पथ का निर्माण कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है ।
2	कराये गए कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, कम से कम 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं कम से कम 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किये जाने का प्रमाण पत्र को विभागीय MIS पर अपलोड जाय ।	REO ROAD - BAHLAMPUR KHAM पथ का कराये गए कार्यों के सभी अवयवों के अवयववार मापी का सत्यापन कनीय अभियंता, सहायक अभियंता एवं कार्यपालक अभियंता द्वारा किया गया है ।

 कनीय अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय	 सहायक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय	 कार्यपालक अभियंता ग्रामीण कार्य विभाग, कार्य प्रमंडल दलसिंहसराय
---	--	--

File : C:\MyMaster\55656\22061919-1.Xls, Section No. : 8, Eqn : $Y = 0 * X^2 + 1.136 * X + 132.5$
Name of Customer : Sona Infracon Pvt Ltd, Name of Work/ Road : REO ROAD - BAHILAMPUR KHAM, Lab Job



29/6/21

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 1.136 * X + 132.5	X = 6300	Y = 7289	(R) RURAL ROAD	Good <4000	Average 4001-5000	Poor >5001
22/6/21	18:36:14	8	0.1	360	0	3600	3860	G	25.65223	85.94094	Normal							
22/6/21	18:36:14	8	0.1	350	20.2	3500	3800	G	25.65262	85.94005	Normal							
22/6/21	18:36:50	8	0.1	370	10.1	3700	3900	G	25.65269	85.93926	Normal							
22/6/21	18:37:0	8	0.1	330	20.2	3300	3881	G	25.65286	85.93827	Curve							
22/6/21	18:37:25	8	0.1	370	20.2	3700	3900	G	25.65227	85.93763	Normal							
22/6/21	18:37:25	8	0.1	380	20.2	3800	3960	G	25.65195	85.9367	Curve							
22/6/21	18:38:0	8	0.1	360	20.2	3600	3800	G	25.65207	85.93572	Normal							
22/6/21	18:38:0	8	0.1	350	20.2	3500	3950	G	25.65207	85.93478	Speed Breaker							
22/6/21	18:38:0	8	0.1	360	20.2	3600	3850	G	25.65202	85.93377	Normal							
22/6/21	18:38:36	8	0.1	360	20.2	3600	3900	G	25.65196	85.93279	Curve							
22/6/21	18:38:36	8	0.1	370	20.2	3700	3900	G	25.65154	85.932	Normal							
22/6/21	18:39:11	8	0.1	350	20.2	3500	3700	G	25.65147	85.93099	Normal							
22/6/21	18:39:11	8	0.1	360	20.2	3600	3800	G	25.65154	85.93003	Normal							
22/6/21	18:39:46	8	0.1	360	20.2	3600	3800	G	25.65166	85.92901	Normal							
22/6/21	18:40:0	8	0.1	360	20.2	3600	3800	G	25.65151	85.92805	Normal							
22/6/21	18:40:0	8	0.1	350	30.3	3500	3700	G	25.65157	85.92608	Normal							
22/6/21	18:40:21	8	0.1	370	30.3	3700	3900	G	25.65163	85.9251	Normal							
22/6/21	18:41:0	8	0.1	330	20.2	3300	3881	G	25.65158	85.92318	Normal							
22/6/21	18:41:0	8	0.1	360	20.2	3600	3750	G	25.6515	85.92217	Normal							
22/6/21	18:41:32	8	0.1	370	20.2	3700	3940	G	25.65147	85.92121	Normal							
22/6/21	18:42:7	8	0.1	370	10.1	3700	3900	G	25.65139	85.92017	Speed Breaker							
22/6/21	18:42:43	8	0.1	350	10.1	3500	3750	G	25.65123	85.91924	Normal							
22/6/21	18:43:0	8	0.1	360	20.2	3600	3850	G	25.6506	85.91877	Normal							
22/6/21	18:43:18	8	0.1	370	20.2	3700	3900	G	25.64973	85.91855	Normal							
22/6/21	18:43:53	8	0.1	360	10.1	3600	3850	G	25.64887	85.918	Normal							
22/6/21	18:44:0	8	0.1	350	20.2	3500	3700	G	25.64825	85.91796	Curve							
22/6/21	18:44:28	8	0.1	360	20.2	3600	3960	G	25.64821	85.91699	Normal							
22/6/21	18:44:28	8	0.1	320	10.1	3200	3500	G	25.64825	85.91594	Speed Breaker							
22/6/21	18:45:0	8	0.1	310	20.2	3100	3400	G	25.64838	85.91502	Normal							
22/6/21	18:45:4	8	0.1	280	20.2	2850	3100	G	25.64834	85.91407	Normal							
22/6/21	18:45:4	8	0.1	370	20.2	3700	3950	G	25.64794	85.91323	Normal							
22/6/21	18:45:4	8	0.1	350	20.2	3500	3780	G	25.64776	85.91222	Normal							
22/6/21	18:45:39	8	0.1	330	10.1	3300	3540	G	25.64762	85.91123	Normal							
22/6/21	18:45:39	8	0.1	330	10.1	3300	3540	G	25.64754	85.91027	Normal							

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event			
22/6/21	18:46:0	8	0.1	350	20.2	3500	3800	G	25.64757	85.90929	Normal			
22/6/21	18:46:14	8	0.1	320	20.2	3200	3767	G	25.64769	85.90833	Normal			
22/6/21	18:46:14	8	0.1	350	10.1	3500	3750	G	25.64793	85.90727	Normal			
22/6/21	18:47:0	8	0.1	370	10.1	3700	3800	G	25.6481	85.90633	Normal			
22/6/21	18:47:25	8	0.1	350	10.1	3500	3700	G	25.64871	85.90577	Normal			
22/6/21	18:47:25	8	0.1	310	10.1	3100	3400	G	25.64912	85.9049	Normal			
22/6/21	18:48:0	8	0.1	320	10.1	3200	3500	G	25.64991	85.90451	Normal			
22/6/21	18:48:0	8	0.1	310	10.1	3100	3450	G	25.65038	85.90367	Normal			
22/6/21	18:48:35	8	0.1	280	10.1	2850	3200	G	25.65044	85.90269	Normal			
22/6/21	18:49:11	8	0.1	310	20.2	3100	3500	G	25.65077	85.90178	Normal			
22/6/21	18:49:11	8	0.1	350	10.1	3500	3700	G	25.65112	85.90089	Normal			
22/6/21	18:49:46	8	0.1	360	10.1	3600	3800	G	25.65127	85.89995	Curve			
22/6/21	18:50:0	8	0.1	350	20.2	3500	3700	G	25.65177	85.89938	Normal			
22/6/21	18:50:21	8	0.1	350	20.2	3500	3800	G	25.6518	85.89838	Normal			
22/6/21	18:50:21	8	0.1	370	20.2	3700	3900	G	25.65173	85.89746	Normal			
22/6/21	18:50:56	8	0.1	360	20.2	3650	3800	G	25.65166	85.89648	Normal			
22/6/21	18:51:0	8	0.1	320	10.1	3200	3500	G	25.65173	85.89545	Normal			
22/6/21	18:51:32	8	0.1	350	10.1	3500	3800	G	25.65194	85.89451	Normal			
22/6/21	18:51:32	8	0.1	340	10.1	3400	3650	G	25.65214	85.89354	Normal			
22/6/21	18:52:7	8	0.1	340	10.1	3400	3800	G	25.65225	85.89259	Speed Breaker			
22/6/21	18:52:42	8	0.1	360	10.1	3600	3950	G	25.65244	85.89165	Speed Breaker			
22/6/21	18:53:0	8	0.1	320	10.1	3200	3500	G	25.65269	85.89067	Normal			
22/6/21	18:53:18	8	0.1	340	10.1	3400	3600	G	25.65293	85.88975	Normal			
22/6/21	18:53:18	8	0.1	350	20.2	3500	3800	G	25.65311	85.8888	Normal			
22/6/21	18:54:0	8	0.1	350	10.1	3500	3700	G	25.6533	85.88776	Normal			
22/6/21	18:54:0	8	0.1	280	10.1	2800	3200	G	25.65356	85.88684	Normal			
22/6/21	18:54:28	8	0.1	360	20.2	3600	3900	G	25.65378	85.88591	Normal			

22/6/21
78