Inspection Report for Flood Damage Report

Ĭ	_		The state of the s
	L	Pate :	
	1 1	Name of PIUs	CEILED, were division, mainar
	2	Name of Block/ Road	Stratya Billas force y wood to Cejas signarily a hote my e tagining a tour
	A.	For Road	:
	1	Damage Location/Chainage	: Af , On, 0,020 ky, 0,050mb, 0,800,8000
	2	Damage Length	: 110 arm
••	3	Nature of Damage	: Costoblete trains blocked due to Breach
	4	Details of Restoration Works	:
	i.	Material being used in Restoration works	Booker Best (402 88008)
	ii.	Equipments/Tools being used in Restoration works	: Jes, Fractor Read Roller
	iii.	Procedure taken up in Restoration works	: Essendhale leuteration frontie
	iv.	Restored Length	: 110000
		•	work found satisfacting
	В	For Bridge	
	,.		
	1	Damage Location/Chainage	:
	2	Domogo Loneth	
	2	Damage Length	•
	3	Nature of Damage	: .
	4	Details of Restoration Works	:
	i.	Material being used in Restoration works	: N, A
	ii.	Equipments/Tools being used in Restoration works	:
	iii	Procedure taken up in Restoration works	:
	iv	. Restored Length	

Situature of JE / AE / EE

Signatue वियोगलक अभियन्त। (Name of Insperior) कार्य विभाग कार्य प्रमण्डल, महना

FDR

YEAR (2021-2022)

GENERAL ABSTRACT OF COST

Restoration of Road from Gijas PMGSY Road to Gijas Siswaniya hote hue Jagiriya tak in Saraiya Block under F.D.R., RWD, Works Division, Muzaffarpur East-1

Block :- Saraiya

District :- Muzaffarpur

<u>SI</u>

Description

Amount

<u>No.</u>

Road Restoration Cost

Rs.

9,14,000.00 87306/

Total

9,14,000.00

Say Rs.

9,14,000.60

872061

3.731 lay

Junior Engineer RWD, Works Section Saraiya

Assitant Engineer RWD, Works Sub-Div. Saraiya Executive Engineer

Executive Engineer RWD, Works Division Muzaffarpur East-1

As Por S.E. RWD (W) Circle Muz.
Latter No. 1179 Bated 01/10/2021
Estimate has been verified byinspecting.
E. E. RWD. AMI) Division. Machine

Estimate has been verified by inspecting

E.E. RWD. (M) Division Making

Technically Sanctioned

nty ?

R, 87

731 KG

one hindred) only

acisional

Superintending Engineer
Rural Works Department
Work Circle, Muzaffarpun

Abstract of Cost & Detailed Estimate for

Restoration of Road from Gijas PMGSY Road to Gijas Siswaniya hote hue Jagiriya tak in Saraiya Block under F.D.R., RWD, Works Division, Muzaffarpur East-1

SI.	so	Item of Work	Quantity	Unit	Rate	Amount	
No.	R		•				
20		The state of the s					
1		2	6	7	8	9	
1		Providing and laying Brick bats,					
		including all taxes etc. all complete job			,		
		as per specification and direction of		1			
		E/I.			2064.5	6 87306	[-y
		As per M.B	422.880	m³	2161.11	913920.00	
2	2 5.6. Labour for laying, fiting and fixing N						
	2.4	pipe with collors in line level and grade					1
		as well providing approved jointing					1
		materials and joints properly filled to		1.		.	1
		make them water proof all completea	1	ľ			
		per specification and direction of E/	N .				\ .
		(Hume pipe available within a lead of	1				1
		40 mtr 1000 mm dia or 100 mm di	1				
-		NP3 H.P				,	
		As per M.B	0.00	m	3992	28 87208	,00
					Total Re	9,13,920	.00

Say Rs.

9,14,000.00

873061

Junior Engineer RWD, Works Section

Saraiya

Assitant Engineer RWD, Works Sub-Div.

Saraiya

Executive Engineer RWD, Works Division

Muzaffarpur East-1