

FDR
YEAR (2021 - 2022)
GENERAL ABSTRACT OF COST


District:--Samastipur


Block:--Sarairanjan


Name of Road:--

Detailed Estimate For Repair of Flood Damaged in L036 To
Dakshin Tola Bahadurpur Armauli

SL. No.	Item of Work	Amount
A	TOTAL COST OF REPAIR DAMAGE	7.814 Lacs 5-932
	Sub Total= (A)	7.814 Lacs
	TOTAL cost of project	7.814 Lacs 5-932


28/11/21
Junior Engineer
RWD (w)Section ,
Sarairanjan


28/11/21
Asstt. Engineer
RWD (w)Sub Division , Sarairanjan


28.12.21
Executive Engineer
RWD (w) Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date.: 05/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai
2. Name of Block – Saraisanjan
3. Name of Road/Bridge – Lo 36 to Dekshin Tola Bahadurpur Amrauli
A. for Road

1. Damage Location/Chainage :
2. Damage Length : 1200m
3. Nature of Damage : Flood
4. Details of Restoration Works : Restoration work to be done.
i. Material being used in Restoration works : Brick Bats.
ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, Roller
iii. Procedure taken up in Restoration works :
iv. Restored Length : 1200m

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration Works :
iii. Procedure taken up in Restoration works :
iv. Restored Length :

[Signature] [Signature]
J.E. 05/4/22 A.E. 05/4/22

[Signature]
Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

[Signature]
Signature
(Name of Inspector)
E. B. Teshing
Rm. Works Division