




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



T01 SH to Harjan Tola



DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Dalsinghsarai	
TOTAL LENGTH OF ROAD	:-	0.106	KM
TOTAL COST OF PROJECT	:-	6.13	Lac

Site Photograph

Name of Road:- T01 SH to Harijan Tola

Block:- Dalsinghsarai

Distt- Samastipur



Alinta
31/10/21
J.E.

40m
31.10.2021

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- T01 SH to Harijan Tola

DISTRICT

SAMASTIPUR

BLOCK

Dalsinghsarai

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BATS	146227.5703
2	GSB	396738.298
	SUB TOTAL:-	542965.868
	12% GST on Total Amount:-	65155.904
	1% lab cess	5429.659
	Total Cost (including GST and Labour Cess)	613551.431

Say 6,13,551 = Rs 61.35 Lakhs

Alinda
31/10/21
Junior Engineer

Usha
31/10/21
Assistant Engineer

Manoj
01/12/21
Executive Engineer

Sanat Kumar
From 10/10/21 to 31/10/21
Landed Thirteen thousand four hundred fifty one Rupees
with an amount over the 12% and 1% cesses

Manoj
01/12/21
बनौदग बनिदग
बनौदग बनिदग
बनौदग बनिदग
10/12/21
T-A

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

BLOCK :- Dalsinghsarai

DISTRICT :- SAMASTIPUR

NAME OF ROAD :- T01 SH to Harijan Tola

S.NO	ITEM OF WORK	AMOUNT	
A		Rs.	613551
	TOTAL COST OF CONSTRUCTION		
	SUB TOTAL	Rs.	613551

[Signature]
31/10/21
Junior Engineer

[Signature]
31.10.21
Assistant Engineer

[Signature]
1.12.21
Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date.:

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division, Dalsinghgarai

2. Name of Block - Dalsinghgarai

3. Name of Road/Bridge - Tol SH to Harigan Tola

A. for Road

1. Damage Location/Chainage : 25.683249° N 85.246127° E

2. Damage Length : 0.106 km

3. Nature of Damage : heavy rain

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick Bats & GSB, B.T. surface.

ii. Equipments/Tools being used in Restoration Works : tipper / roller.

iii. Procedure taken up in Restoration works : GSB Grade 3

iv. Restored Length : 0.106 km.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Alita
25/04/22
J.E.

A.E.
25/04/22
A.E.

Executive Engineer,
R.W.D. Works Division,
Dalsinghgarai

Signature
(Name of Inspector)
E. B. Tishra
Rajwade