

50

Measurement			
applying & laying brick bat with arrange by tractor loading & unloading do all complete job.			
1800	- 2.4 x 3.70 x 0.075	=	0.67
	1 x 1.0 x 0.075	=	0.08
70	- 2 x 0.80 x 0.075	=	0.12
	1 x 1.0 x 1.0 x 0.075	=	0.08
90	- 1.90 x 2.0 x 0.075	=	0.29
70	- 5.30 x 1.90 x 0.075	=	0.76
40	- 9.50 x 4.0 x 0.45	=	17.10
20	- 3.70 x 1.5 + 0.6 + 1 x 0.075	=	0.29
			3
	2.90 x 1.40 x 0.075	=	0.30
	2.0 x 1.50 x 0.075	=	0.23
	1.0 x 0.60 x 0.075	=	0.05
Continuation			

Continuation

