

FDA (2249)

Schedule XLV-Form No. 134

1025. Glycerol to 1000/1000

1000/1000

1000/1000

1000/1000

DIVISION

SUB-DIVISION

Signature: Miss Marybeth G. G. G.

Measurement Book

NO. 387

(Those four lines should be repeated at the commencement of the measurements relating to each work.)

Date of entry	30-10-2021		
(7)	Procting taking and spreading fishbats in forest area of a/c. Gumpale 76		
1x	30x	1.50x0.30 =	9.00m ²
2x	15x	2.10x0.40 =	25.20m ²
1x	20x	1.20x0.60 =	23.20m ²
2x	20x	1.20x0.60 =	40.80m ²
2x	15x	3.00x0.30 =	27.00m ²
3x	20x	2.80x0.45 =	75.60m ²
1x	18x	1.50x0.30 =	8.00m ²
4x	5x	2.50x0.30 =	15.00m ²

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	5x	6.0x	1.5x	0.30 =	13.50m ³
	4x	5x	3.0x	0.30 =	12.00m ³
	5x	5x	1.80x	0.45 =	20.25m ³
	3x	8x	3.0x	0.30 =	21.60m ³
	2x	15x	2.0x	0.45 =	27.00m ³
	3x	7x	1.50x	0.20 =	6.75m ³
	2x	12x	2.5x	0.45 =	27.00m ³
	3x	10x	1.50x	0.30 =	13.50m ³
	1x	8x	3.0x	0.45 =	10.80m ³
	2x	8x	1.80x	0.45 =	17.28m ³
	3x	10x	3x	0.30 =	27.00m ³
	2x	8.0x	2.0x	0.45 =	14.40m ³
	2x	15x	1.60x	0.45 =	21.60m ³
	6x	4.0x	2x	0.60 =	28.80m ³
	4x	6.0x	1.90x	0.40 =	18.24m ³

	2x	10x	3.10x	0.30 =	18.60m ³
					533.05m ³
③ Filling and spreading					
Jacket Sand over					
back brick cap					
- the old concrete slab					
	1x	20x	1.50x	0.10 =	3.00m ³
	2x	15x	2.10x	0.10 =	6.30m ³
	1x	20x	1.90x	0.10 =	3.80m ³
	2x	20x	1.20x	0.10 =	6.80m ³
	2x	15x	3.0x	0.10 =	9.00m ³
	3x	20x	2.80x	0.10 =	16.80m ³
	1x	18x	1.50x	0.10 =	2.70m ³
	4x	5x	2.50x	0.10 =	5.00m ³

Continuation

— 7 —

4

					27 927541.00
			22A	14 4/10/80	10698.00
				14	1301029.00

30-10-2002
25

~~22nd~~
30/10/2021
A.E.

~~30/1/2021~~
EB/RWD/ch-I

Continuation