

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- Haithi Kishanpur Bassam road to Mandal Tol

A. For Road

1. Damage Location Chainage :- 250-254M, 310-366, 450-466.26 M
2. Damage Length :- 82.15 M
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick bats
 - ii. Equipment's/Tools being used in Restoration works:- Tractor-Trolley
 - iii. Procedure taken up in Restoration works:- 159.926 m
 - iv. Restored Length:- 82.15 M


B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges


- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

— 3" —


28/04/22

Signature of JE/AE/EE


20/4/22
RR


28/4/22
Signature
(Name of Inspection)

41A THIKISHANPUR BAR SHAM ROAD TOMADPAL TOLA

(F.P.R.)

Schedule XLV Form No. 134.

Then Thanpur

DIVISION

Then Thanpur

SUB-DIVISION

3065

Measurement Book

			Sub	378833=00
			AE	
			10.5.25	
			T-E.	
			work	
			10.05.00	
			A-E	