## कार्यपालक अभियंता का कार्यालय ग्रामीण कार्य विभाग, कार्य प्रमंडल, त्रिवेणीगंज।

प्रेषक.

पत्रांक 958 अनु त्रिवेणीगंज,

दिनांक 3 6 22

कार्यपालक अभियंता, ग्रामीण कार्य विभाग, कार्य प्रमंडल, त्रिवेणीगंज।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव, बिहार ग्रामीण पथ विकास अभिकरण, पटना।

विषय :-मुख्यमंत्री ग्राम सम्पर्क योजना (MMGSY NDB BRICS) अंतर्गत आवंटन उपलब्ध कराने के संबंध में।

महाशय,

उपर्युक्त विषय के संबंध में कहना है कि मुख्यमंत्री ग्राम सम्पर्क योजना (MMGSY NDB BRICS) अंतर्गत कराये कार्य से संबंधित अधियाचना विहित प्रपत्र में तैयार कर समर्पित है।

अतः अनुरोध है कि आवंटन उपलब्ध कराने की कृपा की जाय।

अन्0 :- 1. यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता ग्रामीण कार्य विभाग वर्ध, प्रमण्डल, त्रिवेणीगंज

							1	
		1	-		N.S	Nam		1
		2021-22	7		Year	e of Division		
		MMGSY-NDB- BRRP-341- Triveniganj	u		Package No	Name of Division :- Triveniganj		
	Total	Maheshpur Dubiyahi PMGSY Path to Sah Tola, Mahadalit Tola, Muslim tola, Mandal Tola.	4		Name of Road			
		Ramanand Prasad Raman	б	Contractor	Name of		MMGS	
	6.440	6.440	6	Length (in Km.)	Admir		Y (NDB)	Rura
	543.55000	543.55000	Amount fin Lacs)	Administrative		Allotmen	l Works L	
	423.74389	423.74389	8	Main Work	Agreeme	MMGSY (NDB) Allotment Requisition Format	<b>Rural Works Department</b>	
	40.20451	40.20451	9	Maintenanc	Agreement Amount (in Lacs)	ion Form	tion Form	nt
34	0.00000	0.00000	10	(in Lacs)	Allotment		at	
Exec BW.D. (	0.00000	0.00000	11	(in Lacs)	Total			
Executive Engineer  OR.W.D. (W.D.) Triveniganj	260.96942	260.96942	12	-	Value of Measurment			
neer reniganj	260.96942	260.96942	13	-	Current Demand in			
anj. \		Ongoing	14	Completion\	Remarks/Actual Dtd. Of			

## FORM GER – 19 – A (See Government of India's Decision (i) below Rule – 150) Form of Utilization Certificate up to 03.06.2022

Executive Engineer RWD, Works Division, Triveniganj

2

Exercised the following Checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Works have been supervised by Executive Engineer / Superintending Engineer.

Periodical inspection has been conduced by A.E. / Executive Engineer / Superintending Engineer.

All other Codal formalities have been observed.

Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.

Construction materials have been tested.