

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- L050 - DW9/914 to Musahar,

A. For Road

1. Damage Location Chainage :-

2. Damage Length :- 104.00m to 98.00m

3. Nature of Damage :-

4. Details of Restoration Works

- Materials being used in restoration works:- Brick bats, Geo Bags, M20 E.C.
- Equipment's/Tools being used in Restoration works:-
- Procedure taken up in Restoration works:- 138.93 cum
- Restored Length:- 104.00m to 98.00m

B. For Bridge

1. Damage Location Chainage :-

2. Damage Length :- 98.00m

3. Nature of Damage :-

4. Details of Restoration Works

- Materials being used in restoration works:- Brick bats, Geo Bags, M20 E.C. Bags
- Equipment's/Tools being used in Restoration works:-
- Procedure taken up in Restoration works:- 138.93 cum
- Restored Length:- 98.00m

C. Requirement Of New CD/ Bridges

i. Name of Road:-

ii. Location/ Chainage:-

iii. Type of CD Work/ Length required:-

Signature of JE/AE/EE

203 E3
20/4/22
RR

12/5/2022

Signature
(Name of Inspection)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
③ Providing and filling brick bats					
1 x 23m x $\frac{2.0+1.0}{2}$ x 0.90 =					31.05m ³
2 x 23m x 1.50 x 0.90 =					62.10m ³
1 x 11m x $\frac{1.50+2.0}{2}$ x $\frac{1.50+0.90}{2}$ =					23.10m ³
2 x 6m x 1.40m x 0.90m =					15.12m ³
1 x 6.0m x 1.40m x 0.90m =					7.56m ³
				Qty =	138.93m ³
				=	138.93m ³
17/5/22				17/5/2022	AK

Abstract of cost					
① supplying of					
MC & CC bag					
290 Nos O.V.T. MBP-①/1					
@ 1043.90/each - Rs					302731.00
② supplying and laying					
CC bag					
2789 Nos O.V.T. MBP-②/2					
@ 179.90/each - Rs					501741.10
③ Providing and filling					
brick bats					
138.93m ³ O.V.T. MBP-③/3					
@ 2004.96/m ³ - Rs					278549.05
C.O. Rs					1083021.19

Continuation

Scanned with CamScanner

1050- Dadaikh to Muskhari

Schedule XLV-Form No. 134

Jhaujharpur

DIVISION

Madhepur

SUB-DIVISION

3097

MEASUREMENT BOOK

Madhepur