

Inspection Report for Flood Damage Work

Date :- 11-5-2022

Name of PIUs :- R.W.D Works Division, Jhanjharpur.

Name of Block/ Road :- Andhra thari

(A) For Road :


1. Damage Location/ Chainage :- Madna to Thathari Paky.
2. Damage Length :- 100 m to 2500 m
3. Nature of Damage :- water logged pots filled by brick bats.
4. Details of Restoration Works :- brick bats filling Qty = 200.11 m³
 - (i) Material being used in Restoration Works :-
 - (ii) Equipment's/ Tools being used in Restoration Works :-
 - (iii) Procedure taken up in Restoration Works :-
 - (iv) Restored Length :- 267.5 m

(B) For Bridge :

1. Damage Location/ Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration Works :-
 - (ii) Equipment's/ Tools being used in Restoration Works :-
 - (iii) Procedure taken up in Restoration Works :-
 - (iv) Restored Length :-

N/A

(S)


Signature of JE/AE/EE


Signature

(Name of Inspection)

Madna - Thathari Patn

Schedule XLV-Form No. 134

Thon Tharpur

DIVISION

Thathari

SUB-DIVISION

3108

MEASUREMENT BOOK

Name of Work—
 Situation of Work—
 Agency by which work is executed—
 Date of Measurement—
 No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
CH- FDR.					
M/W. - Madang To thathari					
Agency:- Departmental work					
Authority:- E.E. R.O.D. Jhampurpuk					
Blow Andirakhar					
Measurement as per D.S.					
① Restoration of Embankment and shoulder with boulder					
$1 \times 2.00 \times 2.00 \times 0.430 = 1.952$					
$1 \times 2.00 \times 3.00 \times 0.340 = 2.01$					
$1 \times 6.00 \times 2.00 \times 0.40 = 4.76$					
$1 \times 9.00 \times 2.50 \times 0.43 = 9.60$					
$1 \times 2.00 \times 1.50 \times 1.25 = 3.66$					
$1 \times 2.00 \times 2.20 \times 0.40 = 1.74$					
$1 \times 1.00 \times 1.00 \times 0.22 = 0.22$					

Continuation

23.99

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1x2.00x1.50x0.490					1.46
1x3.00x2.00x0.490					2.93
1x5.00x2.10x0.40					4.16
1x2.00x1.00x0.30					0.61
1x2.00x2.00x0.30					1.22
1x2.00x1.50x0.58					1.74
1x3.00x1.00x0.270					0.82
1x1.50x1.00x0.180					0.27
1x3.00x2.00x0.490					2.93
1x2.00x1.00x0.30					0.61
1x2.00x1.00x0.18					0.37
1x3.00x2.00x0.490					2.93
1x3.00x2.00x0.30					1.80
1x4.00x1.00x0.20					0.80
1x3.00x1.50x0.49					2.20
1x2.00x1.00x0.61					1.22
1x2.00x2.00x0.270					1.10
1x2.50x2.50x0.40					2.48
1x2.00x1.00x0.58					1.16
1x1.00x3.00x0.61					1.83
1x4.00x3.00x0.40					4.80
1x4.50x2.00x0.30					2.70
1x24.00x1.25x0.20					6.00
1x5.00x1.50x0.270					2.05

Continuation

74.19

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1x2.50x1.30x0.24=					0.79
1x10.50x0.52x0.30=					7.82
1x14.00x1.50x0.30=					6.30
1x12.00x1.50x0.30=					5.49
1x3.00x1.00x0.49=					1.46
1x6.00x1.00x0.27=					1.10
1x54.00x3.50+3.25					
					x 0.30 = 56.70
1x1.00x1.50x0.49=					0.72
1x1.00x1.00x0.18=					0.18
(1) 1x30.00x					
1x3.00x2.00x0.30=					1.83
1x1.00x1.50x0.18=					0.27
1x2.00x1.00x0.27=					0.55
1x47.00x3.50+3.25					
					x 0.25 = 41.12
1x2.00x2.50x0.30=					1.59
					200.10
					m ³
					17/5/22
					7/05/2022

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>Abstract of work</u>					
① Poor and Pilling					
broken beds in					
Ditches, Damage					
Embankment					
& shoulder					
200.10 m ³ of work ③					
CS 2004 = 94 / L. 401192 =					
Add 12% G.S.T (+) L. 48143 =					
Add 10% L. cess (+) L. 4011 = w					
Add S. fees.					
Material					
Bridle Bed					
Qty = 200.10 m ³					
CS 1032 = 00 L. 20,651 = v					
1,473,997 = w					
17/5/22					
17/5/2022					
A.E.					
Continuation					

Continuation