

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Anandpur Thansi

Name of Road :- Motorable of Road :- from Ramkeshan Yadav House To Embankment

A. For Road

1. Damage Location Chainage :- 0.060, 0.090, 0.155, 0.220, 0.280, 0.310
2. Damage Length :- 03 Meter
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick Ball
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:- JIS. A rd
 - iv. Restored Length:-

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-

— S —



Signature of JE/AE/EE



Signature
(Name of Inspection)

M/1003 - Ram location Yard v House to Embankment
Schedule XLV-Form No. 134 (Photocopy work)

FDR

R.W.D. Jhangharpur _____ DIVISION

Andhara Harhi _____ SUB-DIVISION

3110

MEASUREMENT BOOK

