

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Jhanjharpur

Name of Road :- NH 57 to Tajpur

A. For Road


1. Damage Location Chainage :- 20 M, 150, 280, 560, 640, 690, 920
2. Damage Length :- 108
3. Nature of Damage :- Brick bats
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick bats
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:- 90.571 m²
 - iv. Restored Length:- 108

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-


C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:-


21/03/22
18

Signature of JE/AE/EE


2022
25/4/22


S


Signature
(Name of Inspection)

Schedule XLV-Form No. 134

N H S7. to Teli Pur

— DIVISION

EDR

State Division, Surveyor General
Public Works Commission
Executive Engineer

THANJAVUR SUB-DIVISION

317

MEASUREMENT BOOK

Sch. XLV—Form No. 134

2

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1x	5.0	x 0.3	x 0.75	=	1.13
1x	2.5	x 1.50 x 1.70 + 1.60	x 0.65	=	2.60
1x	16.0	x 1.75 + 1.45	x 1.0	=	57.60
				Total	92.80
Less	for H.P. 3 x $\frac{92}{3} (8.30)$ x 2.5 =				2.22
					90.571 m ²
					10.6.22
					I.T.

Abstract of cost

(1) <u>For cut filling brick khati</u> in ditches (excavated) controve- rnent - - - - -	
90.571 m ²	only width 7m & 8/2
90.571 m ² @ ₹ 204.96 / m ²	₹ 181591 = 00
Add 1% GST	₹ 21790 = 00
Add 1% L.C.	₹ 1816 = 00
Add M.Y. S.F	90.59 x 1032 ₹ 9349 = 00
	₹ 214546 = 00

Continuation