



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Samastipur Ujiyarpur Sarairanjan Tajpur Path

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Ujiyarpur	
TOTAL LENGTH OF ROAD	:-	8.000	KM
TOTAL COST OF SURFACE RENEUAL	:-	13.010	Lac
TOTAL COST OF PROJECT	:-	13.010	Lac

06

Site Photographs

NAME OF ROAD : Samastipur Ujiyarpur Sarairanjan Tajpur Path


BLOCK : Ujiyarpur

DISTRICT : Samastipur

1



2



3



4



25/10/2021
02

25/10/21
DE

FLOOD DAMAGED REPORT

GENERAL ABSTRACT OF COST

K:- Ujjarpur

District:- Samastipur

th of Road:- 8.000 KM

ie of Road:- Samastipur Ujjarpur Saralranjan Tajpur Path

No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION :	13.010 Lacs
	TOTAL :	13.010 Lacs

25/10/21
Senior Engineer

25/10/21
Asstt. Engineer

02/12/21
Executive Engineer

SE
RWD

Sanctioned
Approved for Rs 13.01 Lacs Say Thirteen
Lakh one thousand only including 10% CIP
10% only.

10/12/21
T.A.

10/12/21
वसुदेव बसिन्का
आधीन कार्य विभाग
आधीन कार्य, प्रशासकीय

10/12/21

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : Samastipur Ujlyarpur Saralranjan Talpur Path
DISTRICT Samastipur
BLOCK Ujlyarpur
DIVISION Dalsingh Saral
LENGTH OF ROAD (In Km) 8.000

SL No.	DESCRIPTION	Amount	1 % Labour Cess	12 % GST	1% Labour Cess & 12% GST AMOUNT (LAKHS)
PART-A	INITIAL RECTIFICATION INCLUDING SURFACE RENEWAL				
1	Brick Bats	7.501	0.075	0.900	8.476
2	Embankment	0.400	0.004	0.048	0.452
3	GSB	3.448	0.034	0.414	3.896
4	RCC pipe NP-3	0.184	0.002	0.020	0.186
	SUB TOTAL OF SURFACE RENEWAL	11.513	0.115	1.382	13.010
	TOTAL COST OF PROJECT IN LACS =	11.513	0.115	1.382	13.010

25/10/21
JE
RWD

25/10/21
AE
RWD

02/12/21
EE
RWD

Inspection Report for Flood Damage Work

Date: 5.4.22

Dal Singh Sanyal

1. Name of PIUs— Executive Engineer, R.W.D., Works, Division,

2. Name of Block — ^{W. 1st} Same as before W. 1st for Sewerage Treatment Plant

3. Name of Road/Bridge — 2

A. for Road

1. Damage Location/Chainage — 25.767928, 85.71097, 25.768397,

2. Damage Length — 55.711356 0.067 Km

3. Nature of Damage :: 20 to heavy reinforcement

4. Details of Restoration Works : bridge piers, embankment, USB, etc.

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Work done at S. H. S
factory

By: 5/4/22
J.E.

5/4/22
A.E.

05.04.2022
Executive Engineer,
R.W.D. Works Division,
Dal Singh Sanyal

7/4/2022
Signature
(Name of Inspector)
E. C. T. Singh
R. W. D. S. H. S.