




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT





Repair of Road T06 to Maripur

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Mowa	
TOTAL LENGTH OF ROAD	:-	0.060	KM
TOTAL COST OF PROJECT	:-	1.02	Lac

Site Photograph

e of Road:- T06 to Maripur

Block-Morwa



Spined
2/11/21
J.E.

2/11/21
AE

SUMMARY OF COST ESTIMAT FOR THE PROJECT

E OF ROAD :- Repair of Road T06 to Maripur

ICT

SAMASTIPUR

K

Morwa

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BAT	90546.000
	SUB TOTAL:-	90546.000
	12% GST on Total Amount:-	10865.520
	SUB TOTAL:-	905.460
	Total Cost (including GST and Labour Cess	102317.000

[Signature]
21/11/21
Junior Engineer

[Signature]
21/11/21
Assistant Engineer

[Signature]
01/12/21
Executive Engineer

WD (W) Section, Morwa

RWD (W) Sub Division, Morwa

RWD, Works Division, Dalsinghsarai

Sanctioned
For technical work approved for Rs 1,02,317.00 say One
Lak, Two thousand three hundred seven Rupees only
plus 12% GST and 10% CP 18%.

[Signature]
10/12/21
वकील वकील
वकील वकील
वकील वकील

[Signature]
10/12/21
T.A

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST


CK

Morwa

DISTRICT :- SAMASTIPUR

OF ROAD :- Repair of Road T06 to Marlpur

	ITEM OF WORK						AMOUNT	
	TOTAL COST OF CONSTRUCTION					:-	Rs.	102317
					SUB TOTAL	:-	Rs.	102317




Junior Engineer

RWD (W) Section, Morwa



Assistant Engineer
RWD (W) Sub Division,
Morwa



Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Morwa

3. Name of Road/Bridge – To 6 to Manpur

A. for Road

1. Damage Location/Chainage : 0.00m to 60m

2. Damage Length : 60m

3. Nature of Damage : Flood

4. Details of Restoration Works : Restoration to be done.

i. Material being used in Restoration works : Brick Bats. and Earthwork.

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, ~~Lab~~ Roller.

iii. Procedure taken up in Restoration works : Washout by flood to be filled
Brick Bats.

iv. Restored Length : 60m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature
05/4/22
J.E.

Signature
05/4/22
A.E.

Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

Signature
05/04/2022

Signature
05/4/22

Signature
05/4/22

(Name of Inspector)

E. G. Tushar
RWD works division