

Motivated
Turnover
New 2115
Very rough
Rabot
Rolling



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Maheshpatti Babulal Chowk To Dhamua Road Under Ujiyarpur

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Ujiyarpur	
TOTAL LENGTH OF ROAD	:-	3.400	KM
TOTAL COST OF SURFACE RENEUAL	:-	16.184	Lac
TOTAL COST OF PROJECT	:-	16.184	Lac

OK

2.3

Site Photographs

NAME OF ROAD :- Dhamua Chowk To Babulal Chowk

BLOCK :- Ujiyarpur

DISTRICT :- Samastipur

1



2



3



4




5



6



7  Latitude: 23.77813 Longitude: 82.22117 Altitude: 16.5m Time: 15/09/2021 12:13 User: Shreya Chandra	8 
--	---

25/10/2021
 25/10/21
 AE

FLOOD DAMAGED REPORT

GENERAL ABSTRACT OF COST

Block:-- Ujjarpur

District:- Samastipur

Length of Road:-- 3.400 KM

Name of Road:-- Maheshpatti Babulal Chowk To Dhamua Road Under Ujjarpur

SL. No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION	16.184 Lacs
	TOTAL	16.184 Lacs

[Signature]
25/10/21
Junior Engineer

[Signature]
25/10/21
Asstt. Engineer

[Signature]
02.12.21
Executive Engineer

SE
RWD

Technical
approved
for Rs 16.184 Lacs say
87 thousand, Eight hundred and four hundred
only including OHC 12%, C.P 10% only.

[Signature]
10/12/21
T.A

[Signature]
10.12.21
बसोबस बाधक
बाधीय कार्य विचार
कार्य संयोज, प्रयत्नोक्त
10/12/21

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : Maheshpatti Babulal Chowk To Dhamua Road Under Ujjayarpur
DISTRICT : Samastipur
BLOCK : Ujjayarpur
DIVISION : Baisnigh Sarai
LENGTH OF ROAD (in Km) : 3.400

Sl. No.	DESCRIPTION	Amount	1 % Labour Cess	12 % GST	1% Labour Cess & 12% GST AMOUNT (LAKHS)
PART-A	INITIAL RECTIFICATION INCLUDING SURFACE RENEWAL				
1	Brick Bats	14.322	0.143	1.719	16.184
2	Embankment	0.000	0.000	0.000	0.000
3	GSB	0.000	0.000	0.000	0.000
4	RCC pipe NP-3	0.000	0.000	0.000	0.000
	SUB TOTAL OF SURFACE RENEWAL	14.322	0.143	1.719	16.184
	TOTAL COST OF PROJECT IN LACS =	14.322	0.143	1.719	16.184

[Signature]
25/10/2019
JE
RWD

[Signature]
25/10/21
AE
RWD

[Signature]
02-12-2019
EE
RWD

Inspection Report for Flood Damage Work

Date.: 5.4.22

5/4/22

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division,

2. Name of Block – 3rd 211/87

3. Name of Road/Bridge – Maleshatti Babulal Chowk to Dhamua

A. for Road

1. Damage Location/Chainage : 25.778434, 85.829743
25.764396, 85.830226
2. Damage Length : 3.400 Km
3. Nature of Damage : Due to Heavy rain cut
4. Details of Restoration Works : Brick bat, embankment, GSB, RCC pipe.
- i. Material being used in Restoration works :
- ii. Equipments/Tools being used in Restoration Works :
- iii. Procedure taken up in Restoration works :
- iv. Restored Length : 3.400 Km

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
- i. Material being used in Restoration works :
- ii. Equipments/Tools being used in Restoration Works :
- iii. Procedure taken up in Restoration works :
- iv. Restored Length :

Badr
22/4/22
J.E.

5/4/22
A.E.

22/04/2022
Executive Engineer,
R.W.D. Works Division,
Dahabhasgaon

Work done satisfactory

22/4/22
Signature

(Name of Inspector)
E. B. Tashir
RWD works division