




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



NH 103 Halai Bazar to Malpur Chowk tak

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Mowa	
TOTAL LENGTH OF ROAD	:-	0.200	KM
TOTAL COST OF PROJECT	:-	2.37	Lac

Site Photograph

Line of Road:-NH 103 Halai Bazar to Malpur Chowk tak

Block-Morwa



Shard
2/11/21
J.E.

Shard
2/11/21
A8

SUMMARY OF COST ESTIMAT FOR THE PROJECT

IE OF ROAD :- Repair of Road NH 103 Halai Bazar to Malpur Chowk tak

RICT

SAMASTIPUR

CK

Morwa

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BAT	209665.000
	SUB TOTAL:-	209665.000
	12% GST on Total Amount:-	25159.800
	SUB TOTAL:-	2096.650
	Total Cost (including GST and Labour Cess	236921.000

[Signature]
2/11/21
Junior Engineer

[Signature]
24/11/21
Assistant Engineer

[Signature]
01/12/21
Executive Engineer

RWD, Works Division, Dalsinghsarai

Sanctioned
Provisionary estimate for 2,36,921.000 say Two
lakh Three thousand and Ninety two only
including one hundred thousand less 1%

[Signature]
10/12/21
14/12/21
Am and Sec, works

[Signature]
10/12/21
T.A.


FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

DISTRICT :- SAMASTIPUR


CK :- Morwa

E OF ROAD :- Repair of Road NH 103 Halai Bazar to Malpur Chowk tak

								AMOUNT	
NO		ITEM OF WORK							
A								Rs.	236921
		TOTAL COST OF CONSTRUCTION							
								Rs.	236921
						SUB TOTAL		Rs.	236921


Junior Engineer


Assistant Engineer


Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date: 05/4/22

1. Name of PIUs - Executive Engineer, R.W.D., Works, Division, Dalsingh Sarai

2. Name of Block - Morwa.

3. Name of Road/Bridge - NH-103 Halai Bazar to Malpur Chowk via Ranjahi, Bander Hat and Maricha Path.

A. for Road

1. Damage Location/Chainage : 7000m, 7800m, 800m & 10000m

2. Damage Length : 200m

3. Nature of Damage : Flood and heavy Rain.

4. Details of Restoration Works : Restoration to be done.

i. Material being used in Restoration works : Brick Bats and ~~Earthwork~~.

ii. Equipments/Tools being used in Restoration Works : Tractor, Labour, Roller.

iii. Procedure taken up in Restoration works : Wash out by flood and pot holes developed by heavy rains to filled by Brick Bats.

iv. Restored Length : 200m

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature
05/4/22
J.E.

Signature
05/4/22
A.E.

Executive Engineer,
R.W.D. Works Division,
Dalsingh Sarai.

W. M. S. Sarai
Factory

Signature
05/4/22

(Name of Inspector)

E. B. Terbay

Rajwade Bazar