



ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Angar Kerai Path To Angar Kerai

DISTRICT	::	Samastipur	
DIVISION	::	Dalsingh Sarai	
BLOCK	::	Ujiarpur	
TOTAL LENGTH OF ROAD	::	0.791	KM
TOTAL COST OF SURFACE RENEUAL	::	7.738	Lac
TOTAL COST OF PROJECT	::	7.738	Lac

ok

2.3

Site Photographs

NAME OF ROAD :- Angar Kerai Path Se Angar Kerai Path(Lilji)

BLOCK :- Ujiyarpur

DISTRICT : Samastipur

1



2



3




4




5



6



7



8



Handwritten signature
25/10/2021

Handwritten signature
25/10/21
AES

FLOOD DAMAGED REPORT

GENERAL ABSTRACT OF COST

Block:- Ujjarpur District:- Samastipur
Length of Road:- 0.791 KM
Name of Road:- Angar Kerai Path To Angar Kerai

L. No.	Item of Work	Amount
A	TOTAL COST OF CONSTRUCTION	: 7.738 Lacs
	TOTAL	: 8.344 Lacs

7.738

[Signature]
Junior Engineer

[Signature]
25/12/21
Asstt. Engineer

[Signature]
02.12.21
Executive Engineer

SE
RWD
Sanctioned
Technical Party approved for 7,73,800 = 00 say Seven Lacs
Seventy three thousand Eight Hundred Only in
Under the 12.07.18

[Signature]
10/12/21
T.A.

[Signature]
10.12.21
बसोदय बसिष्य
शाहीप कारे विचार
कारे संपुष्ट, प्रयत्नोक्त
AOL
10.12.21

GENERAL ABSTRACT OF COST FOR MAINTENANCE OF ROAD

NAME OF ROAD : Angar Kerai Path To Angar Kerai
 DISTRICT Samastipur
 BLOCK Ujiarpur
 DIVISION Dalsingh Sarai
 LENGTH OF ROAD (in Km) 0.791

S. No.	DESCRIPTION	Amount	1 % Labour Cess	12 % GST	1% Labour Cess & 12% GST AMOUNT (LAKHS)
PART-A INITIAL RECTIFICATION INCLUDING SURFACE RENEWAL					
1	Brick Bats	6.048	0.060	0.728	6.834
2	Supply For Bamboo	0.402	0.004	0.048	0.454
3	Bamboo Piles	0.184	0.002	0.022	0.208
4	Bamboo Waven Chachari	0.202	0.002	0.024	0.229
5	Bamboo Runers	0.012	0.000	0.001	0.014
SUB TOTAL OF SURFACE RENEWAL		6.848	0.068	0.822	7.738
TOTAL COST OF PROJECT IN LACS =		6.848	0.068	0.822	7.738

[Signature]
 20/10/21
 JE
 RWD

[Signature]
 25/10/21
 AE
 RWD

[Signature]
 02-12-21
 EE
 RWD

Inspection Report for Flood Damage Work

Date.: 5.4.22

६५६६६६६६

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division,

2. Name of Block – 3/11/21

3. Name of Road/Bridge – Angkor Korai path to Agour road

A. for Road

1. Damage Location/Chainage 25: 757893, 85: 829176.

2. Damage Length 25: 752814, 85: 878931.

3. Nature of Damage - 1.14 km

3. Nature of Damage - dry to heavy rain

4. Details of Restoration Works Brick bats, Bamboo, chaco

- i. Material being used in Restoration works :
- ii. Equipments/Tools being used in Restoration Works :
- iii. Procedure taken up in Restoration works :
- iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

- i. Material being used in Restoration works :
- ii. Equipments/Tools being used in Restoration Works :
- iii. Procedure taken up in Restoration works :
- iv. Restored Length :

5/4/22
J.E.

5/4/22
A.E.

Executive Engineer,
R.W.D. Works Division,
Dabholkar

Wongdar Satis
factory

Signature
(Name of Inspector)
R. G. Tesh
R.D. Wongdar Satis