


ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT






Repair of Road MMGSY Road to Sahni Tola

ISTRICT	:-	Samastipur	
VISION	:-	Dalsingh Sarai	
LOCK	:-	Dalsinghsarai	
TAL LENGTH OF ROAD	:-	0.114	KM
TAL COST OF PROJECT	:-	1.26	Lac

Site Photograph

Line of Road:-MMGSY ROAD TO SAHNI TOLA

Block-dalsinghsarai



Asinda
28/10/21

SUMMARY OF COST ESTIMAT FOR THE PROJECT

NAME OF ROAD :- Repair of Road MMGSY Road to Sahni Tola

DISTRICT SAMASTIPUR

BLOCK Dalsinghsarai

S.NO	DESCRIPTION	AMOUNT LAKH
1	BRICK BAT	111244.000
	SUB TOTAL:-	111244.000
	Labourless + 12% GST on Total Amount:- <i>1%</i>	13349.280
	SUB TOTAL:-	1112.440
	Total Cost (including GST and Labour Cess)	125786.000

Add 10% Surcharge for

*6410 = 00
Total Rs 1,32,116 = 00 only.*

Mishra
31/10/21
Junior Engineer

[Signature]
29.10.21
Assistant Engineer

[Signature]
01/12/21
Executive Engineer

(W) Section, Dalsinghsarai RWD (W) Sub Division, Dalsinghsarai RWD, Works Division, Dalsinghsarai

*Sanctioned amount 1,32,116 = 00
Presented to me in my approved for 1,32,116 = 00 say one lakh
thirty two thousand one hundred and sixteen only with all
overhead charges and C.Protekt.*

[Signature]
10/11/21
T.A

[Signature]
70/11/21
T.A

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

LOCK :- DALSINGHSARAI

DISTRICT :- SAMASTIPUR

NAME OF ROAD :- Repair of Road MMGSY Road to Sahni Tola

NO	ITEM OF WORK	AMOUNT
A	TOTAL COST OF CONSTRUCTION	Rs. 125706 :-
	SUB TOTAL	Rs. 125706 :-

Alinda
28/10/21

Junior Engineer

RWD (W) Section, Dalsinghsarai

U. S. G.
29.10.21

Assistant Engineer
RWD (W) Sub Division,
Dalsinghsarai

Man
01/12/21

Executive Engineer
RWD, Works Division,
Dalsinghsarai

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Dalsinghsarai

2. Name of Block – Dalsinghsarai

3. Name of Road/Bridge – MMSY Road to Sahni Tola.

A. for Road

1. Damage Location/Chainage : 25.30' N 85.49030675 Δ 25° 38' N & 85° 0' E

2. Damage Length : 0.114 km

3. Nature of Damage : Due to heavy rain cut

4. Details of Restoration Works : Brick Bats

i. Material being used in Restoration works : Brick Bats

ii. Equipments/Tools being used in Restoration Works : Tractor & roller

iii. Procedure taken up in Restoration works : —

iv. Restored Length : 0.114 km

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Abir
05/04/22
J.E.

J. Singh
05/04/22
A.E.

Prakash
05/04/2022
Executive Engineer,
R.W.D. Works Division,
Dalsinghsarai

W. M. Singh
factory
05/04/22
Signature
(Name of Inspector)
E. B. T...
RWD MMSY Dalsinghsarai