

Inspection Report for Flood Damage Work

Date:- 13-11-2021

1. Name of PIUs :- Ex Shailendra Kumar
2. Name of Block :- Karmarkhand
3. Name of Road :- Tikulija Hat se Laxmipur Bhagwati World Bank Road.

A. For Road

1. Damage Location/Chainage :-
2. Damage Length :- 0.315 km
3. Nature of Damage :- 0.315 km
4. Details of Restoration Works :-
 - i. Material being used in Restoration works:-
 - ii. Equipments/Tools being used in Restoration works :- Brick bat, bamboo piles, Rumers, Sand bag.
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored Length :-

B. For Bridge

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Detail of Restoration Works :-
 - i. Material being used in Restoration works :-
 - ii. Equipments/Tools being used in Restoration work :-
 - iii. Procedure taken up in Restoration works :-
 - iv. Restored Length :-

Birend
13/11/21

JE

AE

EE

13/11/21

13/11/21
signature

(Name of Inspector)

Tikulihatt Solamipur Bhagwati
Schedule XLV-Form No. 134
Coold Bank Kooda

Maalkepally DIVISION

Kusumak Kooda SUB-DIVISION

Measurement Book

Name of work -

Situation of work-

Agency by which work is executed-

Date of measurement -

No. and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -					
Location -					
Agency -					

Record measurement -

Item					
1	Priming and laying				
2	Brick bats obtained				
3	from chimney with				
4	mechanical mean Comp.				
5	job at per				
	1x 10.50 x 3.90 x 0.20 =				8.190
	1x 9.00 x 0.90 x 0.15 =				1.215
	1x 5.20 x 0.60 x 0.10 =				0.312
	1x 2.20 x 0.90 x 0.15 =				0.297
	2x 3.00 x 0.90 x 0.15 =				11.475
	1x 2.50 x 0.90 x 0.15 =				11.475
	1x 1.50 x 2.20 x 0.075 =				2.475
	2x 13.80 x 0.60 x 0.10 =				1.656
	1x 15.00 x 1.80 x 0.10 =				2.700
	1x 2.90 x 2.00 x 0.15 =				0.87

Continuation

2
Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	1x	4.30	1.80	0.25	= 1.935
	1x	10.30	1.80	0.15	= 2.781
	1x	6.90	1.40	0.10	= 0.966
	1x	22.00	1.40	0.15	= 4.620
	1x	15.00	2.60	0.13	= 5.070
	1x	3.90	3.00	0.15	= 1.755
	1x	13.00	1.50	0.15	= 2.925
	2x	14.50	0.90	0.15	= 3.915
	1x	4.40	0.90	0.15	= 0.594
	1x	15.00	1.40	0.15	= 3.150
	1x	13.00	1.40	0.20	= 3.640
	2x	8.40	0.60	0.15	= 1.512
	1x	8.40	1.20	0.15	= 1.512
	1x	3.80	2.20	0.15	= 1.368
					= 72.8530

Item 2. Labour for cutting					
6mm to 3mm dia					
bamboo pole to size					
and making shoes and					
climbing etc. as per					
tree spec.					
	3x	314.5	2.75		= 2594.625

Item 3. Labour for filling					
and fixing split bamboo					
woven charcoal in position					
Comp pt job as per					
tree spec.					

Continuation

Abstract of Cost

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Providing and laying Brick bats obtained Qty vide TMRP-① 72.85 m ³ @ Rs 192287/m ³ = 14087- ^u					
② Labour for cutting 62 mm to 75 mm dia semi pipe Qty vide TMRP-② 2594.625 m @ Rs 45.86/m = 119002- ^u					
③ Labour for fitting and fixing Formdia bamboo runner. Qty vide TMRP-③ 948.5 m @ Rs 5.31/m = 5007- ^u					

④ Supply of bamboo at site Qty vide TMRP-④ 590 nos @ Rs 188.39/each = 111148- ^u					
⑤ Labour filling empty cement bag with local sand. Qty vide TMRP-⑤ 2313 nos @ Rs 37.05/each = 85704- ^u Rs = 460948- ^u Add GST @ 12% Rs = 55314- ^u Add L.C @ 1% Rs = 4609- ^u Add S.F @ 10% Rs = 8634- ^u Rs = 529505- ^u					

Prepared
6/11/21
J.E

Checked
6/11/21
H.E

CX

Continuation