




ग्रामीण कार्य विभाग

Rural Works Department, Govt of Bihar

2021-22

FLOOD DAMAGED REPORT



Repair of Bridge Approach H.L. RCC Bridge in Bibhutipur Block
Across Budhi Gandak River Near Mahti.

DISTRICT	:-	Samastipur	
DIVISION	:-	Dalsingh Sarai	
BLOCK	:-	Bibhutipur	
TOTAL LENGTH OF ROAD	:-	0.800	KM
TOTAL COST OF PROJECT	:-	15.86 ^{12.0}	Lac

12.097 lac

Site Photograph

● Bridge:- RCC Bridge in Bibhutipur Block Across Budhi Dandak River Near Mahati

c:- Bibhutipur

Dist:- Samastipur



done
26/10/21
AE.

FDR
YEAR (2021-2022)
GENERAL ABSTRACT OF COST

CK :- BIBHUTIPUR

DISTRICT :- SAMASTIPUR


OF ROAD :- Repair of Bridge Approach H.L. RCC Bridge in Bibhutipur Block Across Budhi Gandak River Near Mahti.

NO	ITEM OF WORK						AMOUNT	
A								
	TOTAL COST OF CONSTRUCTION					:-	Rs.	1586045
					SUB TOTAL	:-	Rs.	1586045

1209712


28.10.21
Junior Engineer

RWD (W) Section, Bibhutipur


28/10/21
Assistant Engineer
RWD (W) Sub Division,
Bibhutipur

Executive Engineer
RWD, Works Division,
Dalsinghsarai

SUMMARY OF COST ESTIMATE FOR THE PROJECT

NAME OF ROAD :- Repair of Bridge Approach H.L. RCC Bridge in Bibhutipur Block Across Budhi Gandak
Near Mahti.

PROJECT

SAMASTIPUR

BLOCK

BIBHUTIPUR

S.NO	DESCRIPTION	AMOUNT LAKH
1	E/W	450515.000
2	BRICK BAT	529652.000
3	SAND FILLING	423412.920
	SUB TOTAL:-	1403579.920
	12% GST on Total Amount:-	168429.590
	1% lab cess	14035.799
	Total Cost (including GST and Labour Cess)	1586045.000

504/12.106

[Signature]
28.10.21

Junior Engineer

[Signature]
28/10/21

Assistant Engineer

[Signature]
02.12.21

Executive Engineer

D (W) Section, Bibhutipur

RWD (W) Sub Division, Bibhutipur

RWD, Works Division, Dalsinghsarai

Sanctioned
for supply of cement for Rs 1210 Lakhs say Twelve
hundred and ten million and one thousand one hundred and
one hundred and one thousand one hundred and one

[Signature]
10/12/21
T.A.

[Signature]
10.12.21
उत्तर प्रदेश सरकार
राजीव गांधी मिशन
आदि योजना, अखिलेश्वर
10.12.21

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs – Executive Engineer, R.W.D., Works Division, Dalsing Sarai

2. Name of Block – Bibhutipur

3. Name of Road/Bridge –

A. for Road

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

B. for Bridge

Repair of Bridge approach H.L.R.C.C Bridge in Bibhutipur across Budhi Gandak river near Mathaithi.

1. Damage Location/Chainage : 0.30 km to 0.80 km

2. Damage Length : 0.50 km

3. Nature of Damage : Flood

4. Details of Restoration Works : Brick bat, earth, sand, bags.

i. Material being used in Restoration works : tractor, Roller

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.50 km

[Signature]
25/04/22
J.E.

[Signature]
05/04/22
A.E.

[Signature]
05.04.2022
Executive Engineer,
R.W.D. Works Division,
Dalsing Sarai

[Signature]
05/04/22
Signature
(Name of Inspector)
G.B. Tashir
RWD Nams Bhandari