

2

Sch. XLV-Form No. 134

Continuation

0.65
1.630
1.807
100

Sch. XLV-Form No. 134

Sch. XLV-Form No. 134					Contents of area
Particulars	Details of actual measurement				
	No.	L.	B.	D.	
<u>Abstract of cost</u>					
① clearing & grubbing -					
QVTMB P-2	0.39	11.22			
② Rs	49496.70			Rs	19304.00
② P/L WBM gr. III -					
QVTMB P-2	11.72	11.72			
② Rs	3913.66			Rs	45868.00
③ P/A Primer Coat -					
QVTMB P-3	157.8				
② Rs	41.23			Rs	4506.00
④ Patch work over WBM using M.S.S. -					
QVTMB P-3	1229.16				
② Rs	210.91			Rs	259242.00
⑤ P/A tack Coat -					
QVTMB P-3	6152.90				
② Rs	13.98			Rs	86018.00
⑥ P/L 25mm thick SDBC -					
QVTMB P-4	183.85				
② Rs	10587.86			Rs	1946578.00
⑦ P/F typical informatory sign board -					
QVTMB P-4					
2 Nos					
② Rs	11130.63			Rs	22261.00

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(18) Const. of subgrade & E. shoulder — all					
QVTMB P-4		1272.90	M ³		
@ Rs 176.75 —					228520
				Rs	2614297.00
Add 1% L.C. (+)				Rs	26143.00
Add 12% GST (+)				Rs	313715.00
Less 1.57% Below G.R.				Rs	2954155.00
				Rs	46380.00
				Rs	2907775.00
Inspected 25.11.20 J.E.					

CASIO

NQM

Singh

Singh

Report

31.03.20

28.05.2020

QC

As per NQM direction

apparatus was kept and

been attached. It has verified by SQM Sri (Ingeni

same has been verified by SQM Sri (Ingeni

Engineer on dated 12.11.2020 and found satisf

direction rectification have been done by S

of concrete. Now, Casting work is already co

Singh on dated 28.05.2020 and found sa

dated 27.05.2020. The same has been veri