Inspection Report for Flood Damage Work : Beecutive Engineer, RND (W) Division, Asoria 1.Name of PIUs : Elkti, Bhirbhiri East to Palasmani 2. Name Of Block / Road A. For Road : cutting at ch-700m 1. Damage Location / Chainage : 75 M 2. Damage Length : crust and Flank washed out. 3. Nature Of Damage 4. Details Of Restoration : soil, local sand, sand Bag, Bricket, Bumbon i) Material Being Used In Restoration : Tractor with trolly eathers. ii) Equipment / Tools Being Used In Restoration Works : Fillingull damaged pertion of crust and flank with above meterial iii) Procedure Taken Up In Restoration Works : 75 M iv) Restored Length B. For Bridge 1.Damage Location / Chainage 2.Damage Length 3. Nature Of Damage Not Applicable. 4. Details Of Restoration

ii) Equipment / Tools Being Used in Restoration Works

iii) Procedure Taken Up In Restoration Works

i) Material Being Used In Restoration

iv) Restored Length

Signature of JE / AE /

Work found satisfactory

Executive Engineer RName WfDliveneotor)

Kishanganj-2

GENERAL ABSTRACT OF COST

NAME OF ROAD :

BHIRBHIRI EAST TO PALASMANI

DISTRICT

BLOCK

ARARIA

SIKTI

DIVISION

ARARIA

LENGTH FOR TEMPORARY RESTORATION

75 M

Si, No.	DESCRIPTION	AMOUNT (LAKHS)
-		1st. Cutting at Ch700 M From Futani Chowk
PART-A	TEMPORARY RESTORATION	STATE OF THE PARTY OF THE PARTY OF
1	EARTHWORK	4,51,240.00
2	SAND BAG FOR PROTECTION	
3	HUME PIPE LAYING	33,188.00
4	BAMBOO PILE	
5	BRICK BAT	12,34,544.00
	Others	-
	SUB TOTAL =	17,18,972.00
	GST @ 12 % =	2,06,277.00
	LABOUR CESS @ 1% =	17,190.00
	SEIGNIORAGE FEE =	75,817.00
	TOTAL =	20,18,256.00
	COST (IN LACS) =	20.183
	GRAND TOTAL (IN LACS) =	20.180

February Lac Eighteen thousand) Only.

Superintending Engineer Rural Works Department

Work Circle Kishangani