

Inspection Report for Flood Damage Work

1. Name of PIUs

: E.E, RWD, Asara

2. Name Of Block / Road

: SKD / Puzara Kachan Raybanshi
to Anand Tola

A. For Road

1. Damage Location / Chainage

: ch-100m to 1800m

2. Damage Length

: 402m

3. Nature Of Damage

: crack & Plank washed out

4. Details Of Restoration

: Soil, Local Sand, Sand by ^{bank} side

i) Material Being Used In Restoration

ii) Equipment / Tools Being Used In Restoration Works

: Tractor with Trolley & others

iii) Procedure Taken Up In Restoration Works

: filling damaged portion

iv) Restored Length

: 402m

B. For Bridge

1. Damage Location / Chainage

:

2. Damage Length

:

3. Nature Of Damage

:

4. Details Of Restoration

:

i) Material Being Used In Restoration

:

ii) Equipment / Tools Being Used in Restoration Works

:

iii) Procedure Taken Up In Restoration Works

:

iv) Restored Length

:

N.A

Work found satisfactory



Signature

Executive Engineer

Name Of Inspector)

Kishanganj-2


30/1/24

Signature of JE / AE / EE


30/1/24

GENERAL ABSTRACT OF COST

NAME OF ROAD : PADARIYA KACHNA RAJBANSHI TOLA TO ANSARI TOLA

DISTRICT ARARIA
BLOCK SIKTI
DIVISION ARARIA
LENGTH FOR TEMPORARY RESTORATION 402 M

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		Cutting at Ch100 M to 1800 M.
PART-A	TEMPORARY RESTORATION	
1	EARTHWORK	22,68,680.00
2	SAND BAG FOR PROTECTION	5,13,937.00
3	HUME PIPE LAYING	-
4	BAMBOO PILE	1,56,065.00
5	BRICK BAT	24,92,445.00
	Others	-
	SUB TOTAL =	54,31,127.00
	GST @ 12 % =	6,51,735.00
	LABOUR CESS @ 1 % =	54,311.00
	SEIGNIORAGE FEE =	1,71,893.00
	TOTAL =	63,09,066.00
	COST (IN LACS) =	63.091
	GRAND TOTAL (IN LACS) =	63.090

[Signature]
RWD
SIKTI

[Signature]
AE
RWD
SIKTI

[Signature]
E
RWD
ARARIA

Ref. E.E. Letter No.....1452.....Dt. 28/4/22

Technically Sanctioned For Rs. 63,09,000/-

(Rupees...Sixty lac Nine thousand -

[Signature]
28/4/22
AE

Only

[Signature]
28/4/22
Superintending Engineer
Rural Works Department
Work Circle Kishanganj