

Inspection Report for Flood Damage Work

Date: 16.04.2022

1. Name of PIUs - Executive Engineer, R.W.D., Works Division, Samastipur

2. Name of Block - Pusa

3. Name of Road/Bridge

A. for Road PDR To Digra panchayat at Rishamper More Banjor
Purwan ke glar se krish: vizyam Kendra Biraule

1. Damage Location/Chainage

0.000 to 3.000,

2. Damage Length

1.75 km

3. Nature of Damage

Potholes & ditches

4. Details of Restoration Works

i. Material being used in Restoration works: Brick bats + G.S. 13,

ii. Equipments/Tools being used in Restoration Works: Tractor, Roller, Hammer
& Chisel

iii. Procedure taken up in Restoration works:

iv. Restored Length:

1.75 km

B. for Bridge

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works

i. Material being used in Restoration works:

ii. Equipments/Tools being used in Restoration Works:

iii. Procedure taken up in Restoration works:

iv. Restored Length:

16/04/22
Rajendra Prasad

J.E.

A.E.

Executive Engineer,
R.W.D. Works Division,
Samastipur

Signature
(Name of Inspector)
E. C. Baidya
Rtd W.D. Division