

Inspection Report of Flood Damage Work

Name of PIUs :- RWD Works Division, Jhanjharpur

Name of Block :- Madhepur

Name of Road :- Mukhya Sadak Dihwar Asthan to Yadavtal

A. For Road

1. Damage Location Chainage :- 200, 220, 300, 500, 590, 630, 700 & 800 to ~~800~~ 1050 KM
2. Damage Length :- \rightarrow ~~0.191~~ KM 143.25
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:- Brick - Bat's
 - ii. Equipment's/Tools being used in Restoration works:- Tractor & JCB
 - iii. Procedure taken up in Restoration works:- 39.37 cum
 - iv. Restored Length:- ~~0.191~~ KM 143.25m

B. For Bridge

1. Damage Location Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works
 - i. Materials being used in restoration works:-
 - ii. Equipment's/Tools being used in Restoration works:-
 - iii. Procedure taken up in Restoration works:-
 - iv. Restored Length:-

C. Requirement Of New CD/ Bridges

- i. Name of Road:-
- ii. Location/ Chainage:-
- iii. Type of CD Work/ Length required:- ——— S ———

Signature of JE/AE/EE


23/4/22
RR


23/4/22
JE


Signature
(Name of Inspection)

Schedule XLV-Form No. 134
Mukhya Sadak Dihwar Astham to Yadav
Tol

Thanjharbur _____ **DIVISION**

Madhebur _____ **SUB-DIVISION**

2099

MEASUREMENT BOOK

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1 x 15.04 x 0.70 x 0.25					2.63 "
					Qty: 39.37 m ³
					J.P. [Signature] 7/5/2022 AE
					J.P. [Signature] 07/05/2022 J-E

Abstract of Cost	
① Providing and filling brick bats	
39.37 m ³ @ U.T. MRP ②	
@ 2004.96/m ³ — Rs.	78935.28
	<u>Rs. 78935.28</u>
Add 12% GST ③ Rs.	9477.23
Add 1% L.L.SS ④ Rs.	789.35
Add 10% S. fee ⑤ Rs.	4062.98
	<u>Rs. 93259.84</u>
	say Rs. 93260.00
	J.P. [Signature] 7/5/2022 AE
	J.P. [Signature] 07/05/2022 J-E

Continuation