

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, दानापुर

पत्रांक :- 1711 (29)

दानापुर/ दिनांक :-

17/11/22

प्रेषक :

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, दानापुर।

सेवा में,

विशेष सचिव,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:- शीर्ष-MR (3054) Under Bihar Rural Road Maintenance Policy-2018 योजना
अंतर्गत आवंटन के अध्याचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि शीर्ष-MR(3054) Under Bihar Rural Road Maintenance Policy-2018 योजना अंतर्गत पथों के आवंटन की अध्याचना विहित प्रपत्र में तैयार कर Signed Hard Copy of Recorded IRI के साथ भेजी जा रही है।

अतः आपसे अनुरोध है कि उक्त योजना का आवंटन उपलब्ध करने की कृपा की जाये ताकि संवेदक का भुगतान किया जा सके।

अनु:-- यथोक्त।

विशवासभाजन

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमण्डल, दानापुर।

17.11.22

17/11/22

Name of Work Division:- Danapur

कार्य पूर्ण हो चुका है
अनुरूप है
एवं सहस्रक अभियंता द्वारा
50 प्रतिशत एवं कार्यभारक
अभियंता द्वारा 10 प्रतिशत
भागी का सलापन कर लिया
गया है।

R.W.D., Works Division, Danapur

Executive Engineer
RWD, Works Division, Danapur


FORM GFR 19-A


(See Government of India's Decision (1) below Rule-150)
Form of utilisation Certificate up to the Month of November-2022

PIU: RWD Works Division, Danapur

Sl No.	Name of Scheme	Sanction No. & Date with Amount	Amount Received (In Rs.)	Particulars
1	Construction of Rural roads under New Maintenance Policy-2018	1. Current Allotment Vide Letter No:- 35 WE Dt:- 13.10.2022	36,02,90,995.00	Certified that out of Rs 36,02,90,995.00 received during the years 2022-23 in favour of Ex. Engineer, RWD, Works Div. Danapur Bihar a sum of Rs 35,83,47,861.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 19,43,134 .00 remaining unutilized at the end to the period under
Total			36,02,90,995.00	

2. Certified that I have satisfied myself that the conditions of which the grants-in-and was Sanctioned have been duly fulfilled/are being fulfilled and that I have exercised the following Checks to see that the money was actually utilized for the purpose for which it was sanctioned
- Kind of Checks exercised
- (Ixi) Works have been supervised by Executive Engineer/Superintending Engineer
 - (Ixi) Periodical inspection has been conducted by Executive Engineer/Superintending Engineer
 - (Ixi) Construction material have been tested
 - (Ixiv) Measurements have been recorded in the MBs and test check conducted by the Assistant
 - (Ixxv) All other codal formalities have been observed
3. Physical Progress achieved:
- (I) Construction of Road works.
 - (ii) Construction of CD work.


D.A.O.
Rural works Deptt.
Works Division, Danapur


Executive Engineer
Rural works Deptt.
Works Division, Danapur

Name of The Road:- Sarai Panchayat Bhawan to Ghusuk Tola Road

Package No:- MR-N/19-20-Danapur/03

Total Length: 1.700 Km

Block:- Danapur

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event	Y = 0 * X + 2 + 0.936 * X + 278.4 X = 5909 Y = 5809		
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD						
13/11/22	10:33:1	38	0.1	310	30.3	3100	3180	G	25.585602	85.18787	Normal			
13/11/22	10:33:36	38	0.1	220	30.3	2200	2337	G	25.585895	85.17928	Speed Breaker			
13/11/22	10:33:36	38	0.1	380	30.3	3800	3835	G	25.586108	85.16985	Normal			
13/11/22	10:34:0	38	0.1	220	30.3	2200	2337	G	25.58621	85.1601	Normal			
13/11/22	10:34:11	38	0.1	250	30.3	2500	2618	G	25.586462	85.1503	Normal			
13/11/22	10:34:11	38	0.1	340	20.2	3400	3460	G	25.586698	85.14023	Normal	(R) RURAL ROAD		
13/11/22	10:34:11	38	0.1	300	20.2	3000	3086	G	25.586685	85.13147	Curve	Good	Average	Poor
13/11/22	10:34:47	38	0.1	390	20.2	3900	3928	G	25.585995	85.12727	Curve			
13/11/22	10:35:0	38	0.1	270	20.2	2700	2805	G	25.585088	85.1249	Normal			
13/11/22	10:35:22	38	0.1	310	10.1	3100	3180	G	25.584213	85.12288	Speed Breaker			
13/11/22	10:36:0	38	0.1	210	30.3	2100	2244	G	25.58328	85.12172	Speed Breaker			
13/11/22	10:36:33	38	0.1	270	30.3	2700	2805	G	25.58268	85.1172	Speed Breaker			
13/11/22	10:37:8	38	0.1	390	30.3	3900	3928	G	25.582705	85.10858	Normal			
13/11/22	10:37:8	38	0.1	340	10.1	3400	3460	G	25.58205	85.9493	Curve			
13/11/22	10:37:8	38	0.1	280	20.2	3544	3595	G	25.58113	85.9325	Normal			
13/11/22	10:38:0	38	0.1	300	10.1	3750	3788	G	25.580487	85.936	Normal			
TOTAL			1.700	5030	393.9	51794	53204							
AVERAGE						3046.705882	3129.647059							

Md. Shadab Alam

AITM

13/11/22

13/11/22

13/11/22

13/11/22

Name of Customer :	Road Construction
Name of Work/ Road :	Sewer/Panchayat Bhawan to GI
Lab Job number :	
Date :	13/11/2022
Section No. :	38


Test Date :	13/11/2022	Road Name :	Sewer/Panchayat Bhawan to GI
Machine No. :	374	Road Type :	(R) RURAL ROAD
Start S No. :		Side :	
Start E No. :		Interval	
Weather :		UV Range :	1244 To 5000 mm/km
Start Location :		Dist Range :	0 To 1000 m
End Location :		Equation :	$Y = 0 \cdot X^2 + 0.936 \cdot X + 278.4$

Print Generate Report and Graph

Rearview Graph

Map View

File : C:\Users\BHRUJA\OneDrive\Desktop\13031750 - Copy.xls, Section No. : 38, Eqn : $Y = 0 \cdot X^2 + 0.936 \cdot X + 278.4$
 Name of Customer : Raj Construction, Name of Work/ Road : Sewer/Panchayat Bhawan to Ghuruk Tola Road, Lab



Md. Shabb Alam

ATM

13/11/22

13/11/22

13/11/22

कार्यपालक अभियंता
 ग्रामीण कर्म विभाग
 कार्य प्रमंडल, बानापुर