

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका-1

पत्रांक

1808

बांका/

दिनांक 11/10/22

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल बांका-1

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण पटना।

विषय- New Maintenance Policy 2018 (MR 3054) योजना अन्तर्गत आवंटन के
संबंध में।

महाशय,

उपर्युक्त विषयक से संबंधित एम0आर0 योजना अन्तर्गत संवेदक द्वारा कराए
गये कार्यों के भुगतान हेतु विहित प्रपत्र में अधियाचित राशि रूपया 95,90000 लाख का
आवंटन उपलब्ध कराने की कृपा की जाय। ताकि संवेदक को भुगतान किया जा सके।

अनु0-

1. अधियाचना प्रपत्र
2. IRI Report

विश्वासभाजन

EP

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1।

ज्ञापांक-

/ बांका,

दिनांक-

प्रतिलिपि- मुख्य अभियंता-4, ग्रामीण कार्य विभाग, बिहार, पटना को सूचनार्थ एवं आवश्यक
कार्रवाई हेतु समर्पित।

कार्यपालक अभियंता,


ग्रामीण कार्य विभाग,
कार्य प्रमंडल बांका-1।


FORM GFR 19-A
(See Government of India's Decision (I) below Rule-150
Form of Utilization Certificate up to the month 11.10.2022
MR New Policy 2018

PU - R.W.D. Works Division Banka-1

Sl. No.	Name of Scheme	Sanction No. & Date with	Amount (in lacs Rs.)	Amount Received (in Lacs Rs.)	Particulars
1.	Construction of Rural Roads under MR New Policy 2018	CFMS Letter No - 22 WE, Dt- 08.08.2022		7247.75393	Certified that out of Rs. 7247.75393 Lacs received upto the years 2021-22 in favour of Ex. Engineer, RWD Bihar, Banka-1 a sum of Rs. 7169.29466 lacs has been utilized for the purpose of MR New Policy 2018 Schemes as given in the margin for 78.45927 Lacs remaining unutilized at the end of the period under.
	Total			7247.75393	

2. Certified that I have satisfied may self that the conditions on which the grants in aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.
 - i. Kinds of Checks exercised-
 - ii. Works have been supervised by Executive Engineer/Superintending Engineer
 - iii. Periodical inspection has been conducted by Executive engineer/Superintending Engineer
 - iv. Construction materials have been tested.
 - v. Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer
 - All other codal formalities have been observed.
3. Physical Progress achieved-
 - i. Construction of Road Works
 - ii. Construction of C.D. Works


Sr. Divisional Accounts Officer
Work Division
Rural Works Department
Banka-1


Executive Engineer
Work Division
Rural Works Department
Banka-1

Executive Director
RWJD Works Trust
Franklin

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग कार्य प्रमंडल बांका.-1

Name of Road-

Construction of Road from
Bhitiya Dhawa Pmgsy Rorad To
Mathgiri.

Name of Scheme -

MR 3054 (New Policy 2018)

Name of Contractor/ Agency -

Lal Suryapal Singh

Length of Road -

2.773 Kms

Project ID -

20703512005

Package No.-

RM/BA/BAN/22/0034

Name of Block -

Fullidumar

Certified that all item
Wise 100% Measurement
has been taken by me

Certified that all item
Wise 50% Measurement
has been taken by me

Certified that all item
Wise 10% Measurement
has been taken by me

10/11/22

Junior Engineer RWD
Work Section - Fullidumar
Works Division - Banka 1

20/11/22

Assistant Engineer RWD
Work Sub Division
Fullidumar
Works Div.- Banka 1

11/11/22

Executive Engineer
Rural Works Dept.
Works Div.- Banka 1

Bhitiya Dhawa PMGSY Road to Mathagiri Tak

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event	Y = 0 * X ^ 2 + 0.866 * X + 501.6	Good	Average	Poor
10/10/22	12:29:44	54	0.1	290	0	2900	3012	G	24.93987	86.74867	Normal	X = 3900			
10/10/22	12:30:0	54	0.1	240	30.3	2400	2580	G	24.94049	86.74928	Normal	Y = 3878			
10/10/22	12:30:20	54	0.1	310	10.1	3100	3186	G	24.94095	86.74992	Normal				
10/10/22	12:43:10	55	0.1	330	0	3300	3359	G	24.9401	86.75125	Normal				
10/10/22	12:43:10	55	0.1	260	20.2	2600	2753	G	24.9402	86.75202	Normal	RURAL ROAD			
10/10/22	12:43:45	55	0.1	290	20.2	2900	3012	G	24.94041	86.75279	Normal				
10/10/22	12:44:0	55	0.1	200	30.3	2000	2233	G	24.94113	86.75337	Culvert	<4000	4001-5000	>5001	
10/10/22	12:44:0	55	0.1	240	20.2	2400	2580	G	24.94192	86.75374	Normal				
10/10/22	12:46:10	56	0.1	320	0	3200	3272	G	24.94451	86.75463	Normal				
10/10/22	12:46:10	56	0.1	250	30.3	2500	2666	G	24.94513	86.75532	Culvert				
10/10/22	12:48:0	56	0.1	380	0	3800	3792	G	24.94533	86.75614	Normal				
10/10/22	12:48:32	56	0.1	390	0	3900	3878	G	24.94563	86.75672	Normal				
10/10/22	12:49:43	56	0.1	300	0	3000	3099	G	24.94591	86.75588	Normal				
10/10/22	12:50:0	56	0.1	340	20.2	3400	3445	G	24.94598	86.75498	Normal				
10/10/22	12:50:18	56	0.1	180	30.3	1800	2060	G	24.94639	86.75406	Normal				
10/10/22	12:50:18	56	0.1	250	20.2	2500	2666	G	24.94685	86.75332	Normal				
10/10/22	12:50:53	56	0.1	270	10.1	2700	2839	G	24.94752	86.75306	Normal				
10/10/22	12:51:0	56	0.1	300	20.2	3000	3099	G	24.94834	86.75332	Normal				
10/10/22	12:51:0	56	0.1	280	20.2	2800	2926	G	24.94919	86.7534	Normal				
10/10/22	12:51:29	56	0.1	270	30.3	2700	2839	G	24.95001	86.75386	Normal				
10/10/22	12:51:29	56	0.1	280	30.3	2800	2926	G	24.9508	86.75421	Normal				
10/10/22	12:52:0	56	0.1	300	30.3	3000	3099	G	24.9516	86.75448	Normal				
10/10/22	12:52:4	56	0.1	230	30.3	2300	2493	G	24.95243	86.75478	Culvert				
10/10/22	12:52:4	56	0.1	380	20.2	3800	3792	G	24.95341	86.75492	Normal				
10/10/22	12:52:39	56	0.1	390	20.2	3900	3878	G	24.95424	86.75517	Normal				

Name of Customer: Lal Suryopal Singh
 Name of Work/ Road: Bhatiya Dhawa PMGSY Road T
 Lab Job number: 54
 Date: 10-10-2022
 Section No. 54


Test Date: 10-10-2022
 Machine No: 407
 Start S No:
 Start E No:
 Weather:
 Start Location:
 End Location:
 Road Name: PMGSY Road To Mathogin Tak
 Road Type: (R) RURAL ROAD
 Side:
 Interval:
 UIV Range: 1500 To 4000 mm/km
 Dist Range: 0 To 0.4 0.1 1000 m
 Equation: $Y = 0.0 \times X^2 + 2.0865 \times X + 501.6$

Print Generate Report and Graph

Redraw Graph

Map View

File: D:\Lat suryopal singh madhygin bump report\Bhatiya Dhawa PMGSY Road to Mathogin Tak.xls, Section No.
 Name of Customer: Lal Suryopal Singh, Name of Work/ Road: Bhatiya Dhawa PMGSY Road To Mathogin Tak, Lab



Lat suryopal singh
 11/10/22
 JE

Lat suryopal singh
 11/10/22
 AE

Lat suryopal singh
 11/10/22

Name of Customer : Lal Surpal Singh
 Name of Work/ Road : Bhatia Dhawa PMGSY Road T
 Lab Job number : 55
 Date : 10-10-2022
 Section No. : 55

Print


Generate Report and Graph

Test Date : 10-10-2022
 Machine No : 407
 Start S No :
 Start E No :
 Weather :
 Start Location :
 End Location :
 Road Name : PMGSY Road To Mathlegin Tek
 Road Type : (R) RURAL ROAD
 Side :
 Urv Range : 1233 To 4000 Interval 1000 min/km
 Dist Range : 0 To 0.7 0.1 - 1000 m
 Equation : $Y = 0.0 \cdot X^2 + 0.866 \cdot X + 501.5$

Redraw Graph

Map View

File : D:\lal surpal singh madhygin bump report\Bhatia Dhawa PMGSY Road to Mathlegin Tak.xls. Section No.
 Name of Customer : Lal Surpal Singh. Name of Work/ Road : Bhatia Dhawa PMGSY Road To Mathlegin Tek. Lab



Calculated
11/10/22
JE

2nd
11/10/22
AF

11/10/22

Name of Customer: Lal Surajpal Singh
Name of Work/Road: Bhatya Dhawa PMGSY Road T
Lab Job number: 76
Date: 10-10-2022
Section No. 76

Test Date: 10-10-2022
Machine No.: 407
Start S. No.:
Start E. No.:
Weather:
Start Location:
End Location:
Road Name: MGSY Road To Mathagiri Tok
Road Type: (R) RURAL ROAD
Side:
Interval:
UV Range: 1060 To 5000 mm/km
Dist Range: 0 To 1.0 0.1 1000 m
Equation: $Y = 0.0 \cdot X^2 + 2.0 \cdot 0.066 \cdot X + 501.5$

File: D:\lal surajpal singh madhygiri bump report\Bhatya Dhawa PMGSY Road to Mathagiri Tok.Xls. Section No.
 Name of Customer: Lal Surajpal Singh, Name of Work/Road: Bhatya Dhawa PMGSY Road To Mathagiri Tok, Lab



Lash
 11/10/22
 JG

JG
 11/10/22