

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक 4923/30

डिहरी / दिनांक 18/04/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,
ब्राडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :-

MR New Maintenance policy-2018 में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

महाप्राय,

उपरोक्त विषय के संबंध में सूचित करना है कि **MR New Maintenance policy-2018** अर्न्तगत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अधियाचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

NKumar
18.04.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

NKB
18/04/23

FORM GFR 19 -A
(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)
Form of Utilisation Certificate upto the Month of April 2023
NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road under MR-03054	10194 16.03.2023	1998.81355	Certificate that out of Rs. 1998.81355 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 1928.87450 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 69.93905 Lacs remaining unutilized at the end of the period under.
TOTAL			1998.81355	

- 2 Certified that I have satisfied myself that the conditions on which the grand-in-aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
- Periodical inspeioin has been conducted by Executive Engineer / Supertending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works.
- Construction of CD works.

Singh
D.A.O. 18/04/23

RWD (W) Div. Dehri

NKumar
18-04-23
Executive Engineer
RWD (W) Div. Dehri

NKb
18/04/23

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri

Requisition formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Sl No.	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No. and Date	Administrative Approval (AA)			Agreement (in Lakh)		Agreement No. and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of FRI (in mm/Km)	Thickness of Bitumin Layer (in mm)	Value of Bitumin Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against Work Done (in Lakh)	Remarks	
					Length (in Km)	Amount (in lakh)	Initial Rectificati on with Surface Renewal (in Lakh)	Five Year Routine Maintenance (in Lakh)												
1																				
1	RM/RO/DEH /220011	PWD Path Darnagar Ambekar Chowk to NH-2C Via Satyar Village (Khandaul)	13121060435	141308.09.2022	3.01	234.206	176.6644	44.58678	RM/RO/DEH/1008MR/3054/MBID/2022-23	30-09-2023			2861.66	25 MM	5%	0	0	147.5912	Surface Complete	
2	RM/RO/DEH /220012	L047-DEHRI YADUNATHPUR ROAD TO BANUA (ODR21)	10301202048	141308.09.2022	1.266	73.291	39.83915	25.879	RM/RO/DEH/1016MR/3054/MBID/2022-23	05.12.2023			2353.46	25MM	5%	0	0	39.04	Surface Complete	
3	RM/RO/DEH /220012	PWD Road Banka More To Paanchayat Sarkar Bhawan Via Jayantipur	13121060434	141308.09.2022	2.65	209.38	139.3962	34.593	RM/RO/DEH/1016MR/3054/MBID/2022-23	05.12.2023			2518.7	25MM	5%	0	0	113.76914	Surface Complete	

विभागीय पत्रांक- 30340(स) 3054-4-04/2020 पार्त 4 5047 दिनांक 23.12.2021 के आलेक में प्रमाणित किया जाता है कि-

- गुणवत्ता पूर्ण एवं विनिर्देशों के अनुरूप कार्य कराने के बाद MB में दर्ज किया गया है।
- सम्बन्धित कार्य कर्मीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

Sis
D.A.O (B/04/23)
RWD (W) Div. Dehri

EXECUTIVE ENGINEER,
RWD, WORKS DIVISION,
DEHRI

18.04.23
MSB
18/04/23

Road Name-PWD Road Banka More To Panchayat Sarkar Bhawan Via Jayantipur

Contractor Name-Basant Kumar

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	TEGORY ROAD	Latitude	ongitude	Event
18/4/23	11:36:20	84	0.1	150	30.3	1500	1915 G		24.56638	83.86342	Normal
18/4/23	11:36:20	84	0.1	160	20.2	1600	2015 G		24.56642	83.86449	Normal
18/4/23	11:36:55	84	0.1	170	30.3	1700	2115 G		24.5664	83.86522	Normal
18/4/23	11:37:0	84	0.1	150	10.1	1500	1915 G		24.56644	83.86625	Normal
18/4/23	11:37:0	84	0.1	210	20.2	2100	2515 G		24.56709	83.86652	Curve
18/4/23	11:37:30	84	0.1	250	30.3	2500	2915 G		24.56793	83.86665	Normal
18/4/23	11:37:30	84	0.1	230	20.2	2300	2715 G		24.56893	83.86668	Normal
18/4/23	11:38:0	84	0.1	250	20.2	2500	2915 G		24.56995	83.86664	Normal
18/4/23	11:38:5	84	0.1	170	30.3	1700	2115 G		24.57072	83.86653	Normal
18/4/23	11:38:5	84	0.1	230	20.2	2300	2715 G		24.57159	83.86642	Curve
18/4/23	11:38:5	84	0.1	160	20.2	1600	2015 G		24.57253	83.86648	Normal
18/4/23	11:38:41	84	0.1	210	30.3	2100	2515 G		24.57336	83.86627	Normal
18/4/23	11:38:41	84	0.1	190	30.3	1900	2315 G		24.57336	83.86627	Normal
18/4/23	11:39:0	84	0.1	320	30.3	3200	3615 G		24.57393	83.86597	Normal
18/4/23	11:39:0	84	0.1	270	30.3	3300	3715 G		24.57482	83.86626	Speed Breaker
18/4/23	11:39:16	84	0.1	150	30.3	3000	3415 G		24.57588	83.86646	Speed Breaker
18/4/23	11:39:16	84	0.1	230	20.2	2300	2715 G		24.57632	83.8661	Normal
18/4/23	11:39:16	84	0.1	250	20.2	2500	2915 G		24.57708	83.86577	Normal
18/4/23	11:40:0	84	0.1	170	30.3	1700	2115 G		24.57796	83.86574	Normal
18/4/23	11:40:0	84	0.1	160	20.2	1600	2015 G		24.57883	83.86566	Normal
18/4/23	11:40:27	84	0.1	210	30.3	2100	2515 G		24.57963	83.86551	Normal
18/4/23	11:40:27	84	0.1	240	20.2	2400	2815 G		24.58041	83.86529	Normal
18/4/23	11:41:2	84	0.1	230	20.2	2300	2715 G		24.58126	83.8654	Normal
18/4/23	11:41:2	84	0.1	150	10.1	1500	1915 G		24.58294	83.86608	Normal
18/4/23	11:41:37	84	0.1	260	30.3	2600	3015 G		24.58384	83.86605	Normal
18/4/23	11:42:0	84	0.1	150	30.3	1500	1915 G		24.58473	83.86614	Normal
18/4/23	11:42:12	84	0.05	150	30.3	1500	1915 G		24.5855	83.86634	Normal

$$Y = 0 \cdot X^2 + 1.000 \cdot X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value

Average IRI-2518.70

Signature
18/04/2023
SE

Y. Prasad
18/04/2023

AE
18/04/23
N.O.E

Name of Customer: Basant Kumar
 Name of Work/Road: Sakar Bhawan Via Jayantipur
 Lab Job number: 54
 Date: 18-04-2023
 Section No: 84

Test Date: 28-04-2016 Road Name: Sakar Bhawan Via Jayantipur
 Machine No: 412 Road Type: (R) RURAL ROAD
 Start S No: Side:
 Start E No: Interval:
 Weather: UV Range: 915 To 5000 1000 mm/km
 Start Location: Besant More Dist Range: 0 To 0.8 0.1 * 1000 m
 End Location: Sakar Bhawan Equation: $Y = 0 * X^2 + 1000 * X + 415.2$


Print Generate Report and Graph

Redraw Graph

Map View

File: E:\Basant Kumar\Jayantipur\Jayantipur.xls Section No: 84 Eqn: $Y = 0 * X^2 + 1000 * X + 415.2$

Name of Customer: Name of Work/Road: Lab Job number



Singh
 18/04/2023
 SE

X. Anand
 18/04/2023
 AE

NKUTMAN
 18.04.23
 EE