

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

पत्रांक 4923/23

डिहरी/दिनांक 18/04/23

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी -सह-सचिव,
ब्राडा,
भूमि विकास बैंक भवन,
बुद्ध मार्ग, पटना।

विषय :-

महाप्राय, **MR New Maintenance policy-2018** में किये गये कार्य के विरुद्ध
आवंटन उपलब्ध कराने के संबंध में।

उपरोक्त विषय के संबंध में सूचित करना है कि **MR New Maintenance policy-2018** अन्तर्गत कराये गये कार्यों के विरुद्ध संवेदक को भुगतान करने हेतु अध्याचना विहित प्रपत्र में भरकर आवश्यक कार्यवाही हेतु समर्पित की जाती है। इस पथ में कोई भी ATR लंबित नहीं है। उक्त पथ का सभी डाटा की प्रविष्टि MIS पर अद्यतन है।

अनु :- यथोक्त।

विश्वासभाजन

NKR
18.04.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, डिहरी

NKR
18/04/23

FORM GFR 19 -A
(SEE GOVERNMENT of India's Decesion (I) below Rule - 150)
Form of Utilisation Certificate upto the Month of April 2023
NEW MAINTENANCE POLICY 2018 MR (3054)

PIU - RWD DEHRI

S.No	Name of Scheme	Sanction No. & Date	Amount Received	Particulars
		With amount(in Rs. Lacs)	(In Rs. Lacs)	
1	Contruction of Rural Road under MR-03054	10194 16.03.2023	1998.81355	Certificate that out of Rs. 1998.81355 Lacs received during the years in favour of Executive Engineer , RWD Dehri Bihar. Sum of Rs. 1928.87450 Lacs has been utilised for the purpose of MR (3054)-2018 Fund hences as given in the margin for which it was sanctioned and that the balance of Rs. 69.93905 Lacs remaining unutilized at the end of the period under.
TOTAL			1998.81355	

- 2 Certified that I have satisfied myself that the conditions on which the grand-in-aid was sanctioned have been duly fulfilled / are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer / Supertending Engineer.
 - Periodical inspectioin has been conducted by Executive Engineer / Supertending Engineer.
 - Construction materials have been tested.
 - Measurements have been recorded in the MBs and test check conducted by the Assistant.
 - All other codal formalities have been observed.
- 3 **Physical Progress achieved :-**
- Construction of Road works.
 - Construction of CD works.

Singh
D.A.O. 18/04/23

RWD (W) Div. Dehri

N Kumar
18-04-23
Executive Engineer
RWD (W) Div. Dehri

NKB
18/04/23

Office of the Executive Engineer, Rural Works Department, Works Division, Dehri
Requisition formate Scheme Head MR (3054) under Bihar road Maintenance Policy-2018 (Rectification and Surface Renewal)

Bihar Road Maintenance Policy-2018 (Rectification and Surface Renewal)																			
Sl No	Package No.	Name of Road	Project Id as per MIS	Administrative Approval (AA) Letter No. and Date	Administrative Approval (AA)		Agreement (in Lakh)		Agreement No and Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/Km)	Thickness of Bitumin Layer (in mm)	Value of Bitumin Content in Percentage	Previous total amount (in Lakh)	Up to Date expenditure as per MIS (in Lakh)	Requisition against Work Done (in Lakh)	Remarks	
					Length (in Km)	Amount (in lakh)	Initial Rectification on Surface Renewal (in Lakh)	Five Year Routine Maintenance (in Lakh)											
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RM/RODEH /220011	PWD Path Damage to Ambedkar Chowk to NH-2C Via Satiya Village (Khandauli)	13121060435	141308.09.2022	3.01	234.206	176.6644	44.58678	RWD/DEHR 108MR/305 4/MBD/202 2-23	30-09-2023		2861.66	25 MM	5%	0	0	147.5912	Surface Complete	
2	RM/RODEH /220012	LM47-DEHRI YADUNATHPUR ROAD TO BANUA (ODR21)	10301202048	141308.09.2022	1.266	73.291	39.83915	25.879	RWD/DEHR 1/16MR/305 4/MBD/202 2-23	05.12.2023		2353.46	25MM	5%	0	0	39.04	Surface Complete	
3	RM/RODEH /220012	PWD Road Banka More To Panchayat Sarkar Bhawan Via Jayantipur	13121060434	141308.09.2022	2.65	209.38	139.3962	34.593	RWD/DEHR 1/16MR/305 4/MBD/202 2-23	05.12.2023		2518.7	25MM	5%	0	0	113.76914	Surface Complete	

विभागीय पत्रांक-मु030(सु) 3054-4-04/2020 पार्त 4 5047 दिनांक 23.12.2021 के आलेख में प्रमाणित किया जाता है कि-
 1. गुणवत्ता पूर्ण एवं विनियमों के अनुरूप कार्य कराने के बाद MB में दर्ज किया गया है।
 2. सम्बंधित कार्य कमीय अभियंता द्वारा कराया गया (100% जांचा गया) सहायक अभियंता द्वारा 50% तथा कार्यपालक अभियंता द्वारा 10% जांचा गया तथा MIS पर Upload किया गया।

सिद्ध
 D.A.O 18/04/23
 RWD (W) Div. Dehri

18.04.23
 EXECUTIVE ENGINEER
 RWD, WORKS DIVISION,
 DEHRI
MSK
 18/04/23

Road Name-PWD Path Daranagar Ambedkar Chowk to NH-2C Via Satiyar Village (Khandail)

Contractor Name-Naval Kishore Singh

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGORY	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
07/04/23	16:35:44	40	0.1	270	0	2700	3115	G	24.57363	83.91046	Normal
07/04/23	16:36:0	40	0.1	260	20.2	2600	3015	G	24.57372	83.91044	Speed Breaker
07/04/23	16:36:20	40	0.1	310	30.3	3100	3515	G	24.57457	83.90977	Speed Breaker
07/04/23	16:36:28	40	0.1	190	30.3	1900	2315	G	24.57523	83.90839	Speed Breaker
07/04/23	16:36:35	40	0.1	230	30.3	2300	2715	G	24.57532	83.90769	Normal
07/04/23	16:36:55	40	0.1	170	30.3	1700	2115	G	24.57599	83.90704	Normal
07/04/23	16:37:0	40	0.1	280	20.2	2800	3215	G	24.57636	83.90671	Normal
07/04/23	16:37:0	40	0.1	270	10.1	2700	3115	G	24.57679	83.90552	Normal
07/04/23	16:37:30	40	0.1	160	10.1	1600	2015	G	24.57667	83.90528	Normal
07/04/23	16:37:30	40	0.1	280	10.1	2800	3215	G	24.57707	83.90442	Normal
07/04/23	16:38:0	40	0.1	300	20.2	3000	3415	G	24.57751	83.9038	Normal
07/04/23	16:38:5	40	0.1	260	20.2	2600	3015	G	24.57819	83.90301	Normal
07/04/23	16:38:5	40	0.1	130	30.3	1300	1715	G	24.57869	83.90182	Normal
07/04/23	16:38:5	40	0.1	330	10.1	3300	3715	G	24.57904	83.90142	Normal
07/04/23	16:38:41	40	0.1	240	10.1	2400	2815	G	24.57983	83.9006	Normal
07/04/23	16:39:0	40	0.1	200	20.2	2000	2415	G	24.58044	83.90022	Normal
07/04/23	16:39:0	40	0.1	270	20.2	2700	3115	G	24.58114	83.89987	Normal
07/04/23	16:39:16	40	0.1	150	30.3	1500	1915	G	24.58219	83.89941	Normal
07/04/23	16:39:16	40	0.1	270	30.3	2700	3115	G	24.58304	83.89873	Normal
07/04/23	16:39:16	40	0.1	240	20.2	2400	2815	G	24.58383	83.89811	Normal
07/04/23	16:40:0	40	0.1	310	20.2	3100	3515	G	24.58461	83.8978	Normal
07/04/23	16:40:0	40	0.1	280	20.2	2800	3215	G	24.58505	83.89829	Normal
07/04/23	16:40:27	40	0.1	290	20.2	2900	3315	G	24.58501	83.89981	Normal
07/04/23	16:40:27	40	0.1	240	20.2	2400	2815	G	24.58506	83.90083	Normal
07/04/23	16:41:2	40	0.1	280	10.1	2800	3215	G	24.58552	83.90131	Normal
07/04/23	16:41:2	40	0.1	150	10.1	1500	1915	G	24.58677	83.90171	Normal
07/04/23	16:41:37	40	0.1	260	20.2	2600	3015	G	24.58738	83.9013	Normal
07/04/23	16:42:0	40	0.1	300	20.2	3000	3415	G	24.58789	83.89962	Normal
07/04/23	16:42:12	40	0.1	220	20.2	2200	2615	G	24.58501	83.89918	Normal
07/04/23	16:42:12	40	0.1	200	20.2	2000	2415	G	24.58755	83.90064	Normal

$$Y = 0 * X^2 + 1.000 * X + 415.2$$

$$X = 2900$$

$$Y = 3315$$

(R) RURAL ROAD

Good Average Poor

IRI Value
Average IRI-2861.66

[Signature]
18/04/2023
JE

X. Prasad
18/04/2023
AE

M. Kumar
18.04.23
EE

Steco Analyser

Name of Customer: Nawal Kishor Singh
Name of Work/Road: H-2C Via Satiyar Village (Bhandal)
Lab Job number: 40
Date: 07-04-2023
Section No.: 40

Test Date	07-04-2023	Road Name	Via Satiyar Village (Bhandal)
Machine No	412	Road Type	(R) RURAL ROAD
Start S No		Side	
Start E No		Interval	
Weather		UV Range	715 To 5000 1000 mm/km
Start Location	pedkar Chowk	Dist Range	0 To 31 01 * 1000 m
End Location	Satiyar Village	Equation	$Y = 0 * X^2 + 1000 * X + 415.2$


Print Generate Report and Graph

Redraw Graph

Map View

File: E:\Nawal Kishor Singh Bump Indicator Report\Satiyar Village\satiyar village.xlsx, Section No.: 40, Eqn: $Y = 0$

Name of Customer: Name of Work/Road: Lab Job number:



[Signature]
18/04/2023
JE

X. Arand
18/04/2023
AE

Mullman
18.04.23
EE